

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8712110287 DOC. DATE: 87/12/04 NOTARIZED: NO DOCKET #
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316
 AUTH. NAME AUTHOR AFFILIATION
 GULDEMOND, W. G. Region 3, Ofc of the Director
 RECIP. NAME RECIPIENT AFFILIATION
 DOLAN, J. E. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele

SUBJECT: Forwards Insp Safety Repts 50-315-87-29 & 50-316/87-29 on
 870929-1110 & notice of violation.

DISTRIBUTION CODE: IE01D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2+21
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD3-3 PD	1 1	WIGGINGTON, D	2 2
INTERNAL:	AEOD	1 1	DEDRO	1 1
	NRR MORISSEAU, D	1 1	NRR/DLPQ/PEB	1 1
	NRR/DOEA DIR	1 1	NRR/DREP/EPB	1 1
	NRR/DREP/RPB	2 2	NRR/DRIS DIR	1 1
	NRR/PMAS/ILRB	1 1	OE LIEBERMAN, J	1 1
	OGC/HDS1	1 1	REG FILE	1 1
	RES DEPY GI	1 1	RGN3 FILE 01	1 1
INTERNAL:	LPDR	1 1	NRC PDR	1 1
	NSIC	1 1		

DEC 4 1987

Docket No. 50-315
Docket No. 50-316

Indiana Michigan Power Company
ATTN: Mr. John E. Dolan
Vice Chairman
Engineering and Construction
1 Riverside Plaza
Columbus, OH 43216

Gentlemen:

This refers to the routine safety inspection conducted by B. L. Jorgensen and J. K. Heller of this office on September 29 through November 10, 1987, of activities at the Donald C. Cook Nuclear Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-58 and No. DPR-74 and to the discussion of our findings with W. G. Smith, Jr., and others of your staff during the course of and at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as described in the enclosed Notice. With respect to this violation the inspection showed that action had been taken to correct the identified violation and to prevent recurrence. Our understanding of your corrective actions is described in Paragraph 6.h of the enclosed inspection report. Consequently, no reply to the violation is required and we have no further questions regarding this matter at this time.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

8712110287 871204
PDR ADOCK 05000315
G PDR

ORIGINAL SIGNED BY W. G. GULDEMOND

W. G. Guldemon, Chief
Reactor Projects Branch 2

Enclosures:

1. Notice of Violation
2. Inspection Reports
No. 50-315/87029(DRP);
No. 50-316/878029DRP)

See Attached Distribution

RIII
Kazmar

RIII
Burgess

RIII
Guldemon

12/4/87

IEU1
11

Indiana Michigan Power Company

2 DEC 4 1987

Distribution

cc w/enclosures:

W. G. Smith, Jr., Plant Manager
DCD/DCB (RIDS)

Licensing Fee Management Branch

Resident Inspector, RIII

Ronald Callen, Michigan

Public Service Commission

EIS Coordinator, USEPA

Region 5 Office

Michigan Department of

Public Health

