

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8712220105 DOC. DATE: 87/12/16 NOTARIZED: NO DOCKET #
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316
 AUTH. NAME AUTHOR AFFILIATION
 HIND, J.A. Region 3, Ofc of the Director
 RECIP. NAME RECIPIENT AFFILIATION
 DOLAN, J.E. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele

SUBJECT: Forwards Mgt Meeting Repts 50-315/87-33 & 50-316/87-33 on 871210.

DISTRIBUTION CODE: IE06D COPIES RECEIVED: LTR \ ENCL SIZE: 6
 TITLE: Environ & Radiological (50 DKT)-Insp Rept/Notice of Violation Respons

NOTES:

	RECIPIENT		COPIES		RECIPIENT		COPIES		
	ID CODE/NAME		LTR	ENCL	ID CODE/NAME		LTR	ENCL	
	PD3-3 LA		1	0	PD3-3 PD		1	1	/
	WIGGINGTON, D		1	1					A
INTERNAL:	AEOD/DOA		1	1	AEOD/DSP		1	1	D
	NMSS/LLOB		1	1	NMSS/SJOB		1	1	D
	NRR/DLPQ/PEB		1	1	NRR/DOEA/EAB		1	1	D
	NRR/DREP/EPB		1	1	NRR/DREP/RPB		2	2	S
	NRR/PMAS/ILRB		1	1	OGC/HDS1		1	1	
	REG FILE 02		1	1	RES.		1	1	
	RES DEPY GI		1	1	RGN3 FILE 01		1	1	
	RGN2/DRSS/EPRPB		1	1	RGN4 MURRAY, B		1	1	
EXTERNAL:	LPDR		1	1	NRC PDR		1	1	
	NSIC		1	1					

TOTAL NUMBER OF COPIES REQUIRED: LTR 23 ENCL 22

R
I
D
S
/
A
D
D
S

DCD

DEC 16 1987

Docket No. 50-315
Docket No. 50-316

Indiana Michigan Power Company
ATTN: Mr. John E. Dolan
Vice Chairman
Engineering and Construction
1 Riverside Plaza
Columbus, OH 43216

Gentlemen:

This refers to the management meeting held in our office in Glen Ellyn, Illinois, on December 10, 1987, which was attended by M. Alexich and other members of your staff. This meeting was held to discuss your proposed changes to the D.C. Cook Radiation Protection Program in response to findings of recent NRC inspections.

The enclosed copy of our report identifies areas discussed during this meeting.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Jack A. Hind
Jack A. Hind, Director
Division of Radiation Safety
and Safeguards

Enclosure: Meeting Reports
No. 50-315/87033(DRSS);
No. 50-316/87033(DRSS)

See Attached Distribution

RII
(initials)
Gill/jlr
12/16/87

RIII
(initials)
Greger

RII *MOS*
(initials)
Burgess
12/16/87

RII
(initials)
Shafer

Y25
RIII
(initials)
Hind
12/16/87

IE 06
1/1

Indiana Michigan Power Company

2

DEC 16 1987

Distribution

cc w/enclosure:
W. G. Smith, Jr., Plant Manager
DCD/DCB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII
Ronald Callen, Michigan
Public Service Commission
EIS Coordinator, USEPA
Region 5 Office
Michigan Department of
Public Health