REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8802220206 DOC. DATE: 88/02/19 NOTARIZED: NO DOCKET # FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316 AUTH. NAME AUTHOR AFFILIATION MALLETT, B. S. Region 3, Ofc of the Director RECIP. NAME RECIPIENT AFFILIATION DOLAN, J. E. Indiana Michigan Power Co.

SUBJECT: Forwards Insp Repts 50-315/88-06 & 50-316/88-06 on 880119-20 & notice of violation.Notice withheld (ref 10CFR 73.21).

DISTRIBUTION CODE: IEO4D COPIES RECEIVED:LTR \perp ENCL \perp SIZE: d + jTITLE: Safeguards Inspection Rpt/NOV Response (50 DKT)-Publicly Available

NOTES:

1

Ĩ,

Į.,

	RECIPIENT ID CODE/NAM PD3-3 LA WIGGINGTON, D	1E	COPIE LTTR 1 1		RECIPIENT ID CODE/NAME PD3-3 PD	COP I LTTR 1	
INTERNAL:	AEOD/DOA NRR4DRIS/SIB REG_EILE	02	1 1 1	0 1 1	NRR/DRIS/SGB NRR/PMAS/ILRB RGN3 FILE 01	1. 1 1	1 0 1
EXTERNAL:	LPDR NSIC		1 1	1 1	NRC PDR	1	1



SAFEGUARDS INFORMATION

FEB 1 9 1988

Docket No. 50-315 Docket No. 50-316

Indiana Michigan Power Company ATTN: Mr. John E. Dolan Vice Chairman Engineering and Construction 1 Riverside Plaza Columbus, OH 43216

8802220206 880219

PDR

ADDCK 05000315

PDR

Gentlemen:

This refers to the special safeguards inspection conducted by Mr. T. J. Madeda of this office on January 19-20, 1988, of activities at the D.C. Cook Nuclear Plant, Units 1 and 2 authorized by NRC Operating Licenses No. DPR-58 and No. DPR-74 and to the discussion of our findings with Mr. W. G. Smith, Jr. and other members of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required. Inspection results also identified one concern that requires your attention. This concern is identified in Section 5 of the enclosed report. We request a written response to this concern within 30 days of your receipt of this letter.

Areas examined during this inspection concern a subject matter which is exempt from disclosure according to Part 73, Title 10, Code of Federal Regulations, Section 73.21(c)(2). This information must be handled and protected in accordance with the provisions of 10 CFR 73.21. Consequently, the enclosure to this letter, our report of the inspection, and your response to the violation identified in the enclosure to this letter will not be placed in the NRC Public Document Room. Therefore, your statement of corrective action regarding the violation identified in the enclosure and your response to the concern noted in Section 5 of the enclosed report should be submitted as a separate enclosure to your transmittal letter in the manner prescribed.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.



TEI

ì

Enclosure contains SAFEGUARDS INFORMATION Upon separation this page is Decontrolled

SAFEGUARDS INFORMATION

·

e.

. .

. .

.



\$

SAFEGUARDS INFORMATION

Indiana Michigan Power Company

2

FEB 1 9 1388

F

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Aucel, Multell

Bruce S. Mallett, Ph.D., Chief Nuclear Materials Safety and Safeguards Branch

Enclosures: 1. Notice of Violation 2. Inspection Reports No. 50-315/88005(DRSS); No. 50-316/88006(DRSS) (UNCLASSIFIED SAFEGUARDS INFORMATION)

cc w/enclosures: W. G. Smith, Jr., Plant Manager NRR/DRIS/SGB NRR/DRIS/S1B



cc w/enclosures, w/o UNCLASSIFIED SAFEGUARDS INFORMATION: DCD/DCB (RIDS) Licensing Fee Management Branch Resident Inspector, RIII Ronald Callen, Michigan Public Service Commission EIS Coordinator, USEPA Region 5 Office Michigan Department of Public Health



Enclosure contains SAFEGUARDS INFORMATION Upon separation this page is Decontrolled