Dockets Nos. 50-315 and 50-316

Mr. Milton P. Alexich, Vice President Indiana Michigan Power Company c/o American Electric Power Service Corporation 1 Riverside Plaza Columbus, Ohio 43216

SUBJECT: NRC BULLETIN 88-01 (TACS NOS. 67655 and 67656)

By letter dated February 5, 1988, the NRC issued Bulletin 88-01. The purpose of the bulletin was to provide information on Westinghouse series DS circuit breakers and safety concerns associated with their use and to request that addressees using these breakers in Class 1E service perform and document inspection of the welds on the pole shafts and inspection of the alignment in the breaker closing mechanism.

By letter dated April 13, 1988, you provided your response to NRC Bulletin 88-01. Your response indicated that the Westinghouse breakers used at D.C. Cook are type DB-50; Westinghouse DS/OSL type circuit breakers are not used at D.C. Cook.

Based on your April 13, 1988 response to NRC Bulletin 88-01, we consider our review complete. This completes our action under TACS Nos. 67655 and 67656.

Sincerely,

original signed by

John F. Stang, Project Manager Project Directorate III-1 Division of Reactor Projects - III, IV, V & Special Projects

cc: See next page

DISTRIBUTION
DOCKET FILE
NRC & LOCAL PDRs
PD31 GRAY FILE
GHOLAHAN
RINGRAM
JSTANG

DHOOD DSELLERS

JSTANG OGC EJORDAN BGRIMES ACRS (10)

PD31VAM: DRSP JSTANC 7/ 1/88 PD31/PD:DRSP MVIRGILIO 7/6/88 DFOI 10

8807130103 880704 PDR ADDCK 05000315 Q PNU





UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555 July 6. 1988

Dockets Nos. 50-315 and 50-316

Mr. Milton P. Alexich, Vice President Indiana Michigan Power Company c/o American Electric Power Service Corporation 1 Riverside Plaza Columbus, Ohio 43216

SUBJECT: NRC BULLETIN 88-01 (TACS NOS. 67655 and 67656)

By letter dated February 5, 1988, the NRC issued Bulletin 88-01. The purpose of the bulletin was to provide information on Westinghouse series DS circuit breakers and safety concerns associated with their use and to request that addressees using these breakers in Class 1E service perform and document inspection of the welds on the pole shafts and inspection of the alignment in the breaker closing mechanism.

By letter dated April 13, 1988, you provided your response to NRC Bulletin 88-01. Your response indicated that the Westinghouse breakers used at D.C. Cook are type DB-50; Westinghouse DS/OSL type circuit breakers are not used at D.C. Cook.

Based on your April 13, 1988 response to NRC Bulletin 88-01, we consider our review complete. This completes our action under TACS Nos. 67655 and 67656.

Je 7 Jm

inberely,

John F. Stang, Project Manager Project Directorate III-1

Division of Reactor Projects - III, IV, V

& Special Projects

cc: See next page

Mr. Milton Alexich Indiana Michigan Power Company

cc: Regional Administrator, Region III U.S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

Attorney General Department of Attorney General 525 West Ottawa Street Lansing, Michigan 48913

Township Supervisor Lake Township Hall Post Office Box 818 Bridgeman, Michigan 49106

W. G. Smith, Jr., Plant Manager Donald C. Cook Nuclear Plant Post Office Box 458 Bridgman, Michigan 49106

U.S. Nuclear Regulatory Commission Resident Inspectors Office 7700 Red Arrow Highway Stevensville, Michigan 49127

Gerald Charnoff, Esquire Shaw, Pittman, Potts and Trowbridge 2300 N Street, N.W. Washington, DC 20037

Mayor, City of Bridgeman Post Office Box 366 Bridgeman, Michigan 49106

Special Assistant to the Governor Room 1 - State Capitol Lansing, Michigan 48909

Nuclear Facilities and Environmental Monitoring Section Office Division of Radiological Health Department of Public Health 3500 N. Logan Street Post Office Box 30035 Lansing, Michigan 48909

Donald C. Cook Nuclear Plant

Mr. S. Brewer American Electric Power Service Corporation 1 Riverside Plaza Columbus, Ohio 43216