

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

CESSION NBR:8810050322 DOC.DATE: 88/09/19 NOTARIZED: NO DOCKET #
 FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316

AUTH.NAME AUTHOR AFFILIATION
 AXELSON,W.L. Region 3, Ofc of the Director
 RECIP.NAME RECIPIENT AFFILIATION
 ALEXICH,M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele

SUBJECT: Forwards Safety Insp Repts 50-315/88-20 & 50-316/88-23 on
 880726-0907.No violations noted.

DISTRIBUTION CODE: IE01D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 2+16
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD3-1 PD	1 1	STANG,J	2 2
INTERNAL: AEOD	1 1	DEDRO	1 1
NRR MORISSEAU,D	1 1	NRR/DLPQ/PEB 11	1 1
NRR/DLPQ/QAB 10	1 1	NRR/DOEA DIR 11	1 1
NRR/DREP/EPB 10	1 1	NRR/DREP/RPB 10	2 2
NRR/DRIS DIR 9A	1 1	NRR/PMAS/ILRB12	1 1
NUDOCS-ABSTRACT	1 1	OE-LIEBERMAN,J	1 1
OGC/HDS1	1 1	REG FILE 02	1 1
RES/DSIR DEPY	1 1	RGN3 FILE 01	1 1
INTERNAL: LPDR	1 1	NRC PDR	1 1
NSIC	1 1		

TOTAL NUMBER OF COPIES REQUIRED: LTTR 23 ENCL 23



DCD

SEP 19 1988

Docket No. 50-315
Docket No. 50-316

Indiana Michigan Power Company
ATTN: Mr. Milton P. Alexich
Vice President
Nuclear Operations Division
1 Riverside Plaza
Columbus, OH 43216

Gentlemen:

This refers to the routine safety inspection conducted by B. L. Jorgensen, J. K. Heller and J. M. Shine of this office on July 26 through September 7, 1988, of activities at the Donald C. Cook Nuclear Plant, Units 1 and 2 authorized by NRC Operating Licenses No. DPR-58 and No. DPR-74 and to the discussion of our findings with W. G. Smith, Jr., and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, and the enclosed inspection report will be placed in the NRC Public Document Room.


We will gladly discuss any questions you have concerning this inspection.


Sincerely,


W. L. Axelsson, Chief
Reactor Projects Branch 2

Enclosures: Inspection Reports
No. 50-315/88020(DRP);
No. 50-316/88023(DRP)

See Attached Distribution

RIII

Burgess/jlr
9/19

RIII

Jablonski
yes

RIII

Axelsson

1/1
TFOI

88-10322 880919
PLC DOCK 05000315
PDC

SEP 19 1988

Distribution

cc w/enclosures:

W. G. Smith, Jr., Plant Manager

DCD/DCB (RIDS)

Licensing Fee Management Branch

Resident Inspector, RIII

Ronald Callen, Michigan

Public Service Commission

EIS Coordinator, USEPA

Region 5 Office

Michigan Department of

Public Health

J. Stang, LPM