

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8904110047 DOC.DATE: 89/03/24 NOTARIZED: NO DOCKET #
 FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316
 AUTH.NAME AUTHOR AFFILIATION
 GREGER,L.R. Region 3, Ofc of the Director
 RECIP.NAME RECIPIENT AFFILIATION
 ALEXICH,M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele

SUBJECT: Forwards Safety Insp Repts 50-315/89-12 & 50-316/89-12 on I
 890308-10.No violations noted.

DISTRIBUTION CODE: IE06D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 2+7 D
 TITLE: Environ & Radiological (50 DKT)-Insp Rept/Notice of Violation Respons S

NOTES:


	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	
	PD3-1 LA	1 0	PD3-1 PD	1 1	/
	STANG,J	1 1			A
INTERNAL:	AEOD/DSP	1 1	NMSS/LLOB 5E4	1 1	D
	NMSS/SGDB 4E4	1 1	NRR/DLPQ/PEB 11	1 1	D
	NRR/DOEA/EAB 11	1 1	NRR/DREP/EPB 10	1 1	S
	NRR/DREP/RPB 10	2 2	NRR/PMAS/ILRB12	1 1	
	NUDGS-ABSTRACT	1 1	OGC/HDS1	1 1	
	REG FILE 02	1 1	RES	1 1	
	RGN3 DRSS/RPB	2 2	RGN3 FILE 01	1 1	
	RGN2 COLLINS,D	1 1	RGN4 MURRAY,B	1 1	
EXTERNAL:	EG&G SIMPSON,F	2 2	LPDR	1 1	
	NRC PDR	1 1	NSIC	1 1	

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 26 ENCL 25

I
D
S
/
A
D
D
S
/
A
D
D
S
/
A
D
D
S



MAR 24 1989

Docket No. 50-315
Docket No. 50-316

Indiana Michigan Power Company
ATTN: Mr. Milton P. Alexich
Vice President
Nuclear Operations Division
1 Riverside Plaza
Columbus, OH 43216

Gentlemen:

This refers to the special safety inspection conducted by Mr. C. F. Gill of this office on March 8-10, 1989, of activities at D. C. Cook Nuclear Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-58 and No. DPR-74 and to the discussion of our findings with Mr. W. G. Smith, Jr. and others of your staff at the conclusion of the inspection.

This inspection was conducted to review the circumstances surrounding your identification that the Turbine Room Sump had not been sampled and analyzed in accordance with the Technical Specification surveillance requirements. The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,


L. Robert Greger, Chief
Reactor Programs Branch

Enclosure: Inspection Reports
No. 50-315/89012(DRSS); and
No. 50-316/89012(DRSS)

See Attached Distribution

^{yes}
RIII
(G)
Gill/ib
3/23/89

RIII
WGS
Snell
3/23/89

RIII
Burgess
3/23/89

RIII
(M)
Greger
3/24

IEO6
11

8904110047 890324
FDR ADOCK 05000315
Q

Indiana Michigan Power-Company

2

MAR 9 4 1989

Distribution

cc w/enclosure:

W. G. Smith, Jr., Plant Manager
DCD/DCB (RIDS)

Licensing Fee Management Branch
Resident Inspector, RIII

Ronald Callen, Michigan
Public Service Commission

EIS Coordinator, USEPA

Region 5 Office

Michigan Department of
Public Health