

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8908170615 DOC.DATE: 89/08/09 NOTARIZED: NO DOCKET #
 FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315
 AUTH.NAME . AUTHOR AFFILIATION
 COOPER,R.W., Region 3, Ofc of the Director
 RECIP.NAME RECIPIENT AFFILIATION
 ALEXICH,M.P. Indiana Michigan Power Co.

SUBJECT: Forwards Insp Rept 50-315/89-20 on 890522-25 & 0707. & notice of violation.

DISTRIBUTION CODE: IE01D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 2+7
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD3-1 PD	1 1	GIITTER,J.	1 1
INTERNAL:	AEOD	1 1	AEOD/DEIIB	1 1
	AEOD/TPAD	1 1	DEDRO	1 1
	NRR SHANKMAN,S	1 1	NRR/DEST DIR	1 1
	NRR/DLPQ/PEB	1 1	NRR/DOEA DIR 11	1 1
	NRR/DREP/EPB 10	1 1	NRR/DREP/RPB 10	2 2
	NRR/PMAS/ILRB12	1 1	NUDOCS-ABSTRACT	1 1
	OE LIEBERMAN,J	1 1	OGC/HDS1	1 1
	REG-FILE 02	1 1	RES MORISSEAU,D	1 1
	RGN3 FILE 01	1 1		
EXTERNAL:	LPDR	1 1	NRC PDR	1 1
	NSIC	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 23 ENCL 23

R
I
D
S
/
A
D
D
S

AUG 9 1989

Docket No. 50-315

Indiana Michigan Power Company
ATTN: Mr. Milton P. Alexich
Vice President
Nuclear Operations Division
1 Riverside Plaza
Columbus, OH 43216

Gentlemen:

This refers to the special safety inspection conducted by Mr. H. A. Walker of this office on May 22-25 and July 7, 1989, of activities at the D. C. Cook Nuclear Plant, Unit 1 authorized by Operating License No. DPR-58 and to the discussion of our findings with Mr. J. Droste and others of your staff at the conclusion of the inspection. The purpose of this inspection was to follow up on incidents related to the overspeed failures of Unit 1 Emergency Diesel Generators.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required. In addition, one instance was noted where appropriate action was not taken to assure that inspection and test requirements were met. In your response, please describe the action you have taken on this matter as described in Paragraph 2.3.2 of this report.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

8908170615 890809
PDR ADOCK 05000315
Q PNU

"Original Signed by R. W. Cooper II"
R. W. Cooper, II, Chief
Engineering Branch

Enclosures:

1. Notice of Violation
2. Inspection Report
No. 50-315/89020(DRS)

See Attached Distribution

RIII
HAW
Walker/jk
08/08/89

RIII *(yes)*
Liz
Burgess
08/14/89

RIII
Mult For
Jablonski
08/9/89

RIII
RCR
Cooper
08/9/89

4201

Indiana Michigan Power Company

2

AUG 9 1989

Distribution

cc w/enclosures:

W. G. Smith, Jr., Plant Manager

DCD/DCB (RIDS)

Licensing Fee Management Branch

Resident Inspector, RIII

Ronald Callen, Michigan

Public Service Commission

EIS Coordinator, USEPA

Region 5 Office

Michigan Department of

Public Health