



Indiana Michigan  
Power Company  
Cock Nuclear Plant  
One Cook Plant  
Bridgman, MI 49106  
616 465 5901



March 18, 1999

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

Operating License DPR-58  
Docket No. 50-315

Document Control Manager:

In accordance with the criteria established by 10 CFR 50.73 entitled Licensee Event Report System, the following report is being submitted:

LER 315/99-004-00, "Failure to Perform Technical Specification Surveillance Analyses of Reactor Coolant Chemistry with Fuel Removed."

The following commitment has been identified:

- The root cause investigation for this event has not been completed. Based on the results of this investigation, additional corrective actions, including preventive actions may be developed. It is anticipated that, if significant changes are identified, supplemental information regarding corrective and preventive actions will be provided in an update to this LER.

Sincerely,

R. P. Powers  
Vice President

/mbd  
Attachment

c: J. E. Dyer, Region III  
P. A. Barrett  
D. F. Kunsemiller  
R. Whale  
D. Hahn  
Records Center, INPO  
NRC Resident Inspector

9903260063 990318  
PDR ADOCK 05000315  
S PDR

11  
11  
IE22