



Indiana Michigan  
Power Company.  
Cook Nuclear Plant  
One Cook Plant  
Bridgman, MI 49106  
616 465 5901



April 1, 1999

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

Operating License DPR-58  
Docket No. 50-315

Document Control Manager:

In accordance with the criteria established by 10 CFR 50.73 entitled Licensee Event Report System, the following report is being submitted:

LER 315/99-007-00, "Calculations Show that the Divider Barrier Between Upper and Lower Containment Volumes May Be Overstressed"

The following commitment has been identified in this submittal:

- Structural engineers are currently developing appropriate analyses of the loads and stresses on the steam generator enclosures. The results of these analyses will determine if an overstressed condition could have occurred and, if so, the safety significance of the overstressed condition.

Sincerely,

A handwritten signature in black ink, appearing to read 'R. P. Powers', is written over a horizontal line.

R. P. Powers  
Vice President

/mbd  
Attachment.

c: J. E. Dyer, Region III  
P. A. Barrett  
D. F. Kunsemiller  
R. Whale  
D. Hahn  
Records Center, INPO  
NRC Resident Inspector

9904070423 990401  
PDR ADOCK 05000315  
S PDR

70007

IE22

