CATEGORY

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9906070042 DOC.DATE: 99/06/01 NOTARIZED: NO DOCKET # FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315 AUTH:NAME AUTHOR AFFILIATION BAKKEN,A.C. Indiana Michigan Power Co. RECIP.NAME RECIPIENT AFFILIATION Records Management Branch (Document Control Desk)

SUBJECT: Forwards LER 99-S003-00, re nonconforming vital area barriers.Commitments made by util are listed.

DISTRIBUTION CODE: IE74T COPIES RECEIVED:LTR _ ENCL / SIZE: + . TITLE: Safeguards Phys Sec Event Pt. 73.71 (Public Available)

NOTES:

	RECIPIENT ID CODE/NAME STANG,J		COPIES LTTR ENCL 1 0		RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	
INTERNAL:	AEOD/SPD/RR NMSS/FCSS/F0 RGN3		1 1 1	1 1 1	NUDOCS FULLTEXT	1 1	1
EXTERNAL:	NRC PDR		1	1			

NOTE TO ALL "RIDS" RECIPIENTS: PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LIS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTR DESK (DCD) ON EXTENSION 415-2083

FULI	L TEXT (CON	VERSION	REQUIRED		e		
TOTAL	MBER	OF	COTTES	RF ^{TT} IRED:	LTTR	7	ENCL	6

Indiana Michigar Power Company CookNuclear Plant One Cook Plant Bridgman, Mi 49106 616 465 5901



June 1, 1999

United States Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

> Operating License DPR-58 Docket No. 50-315

Document Control Manager:

In accordance with the criteria established by 10CFR73, Appendix G, paragraph I(c) and 10CFR73.71(d), the following report is being submitted:

LER 315/99-S003-00, "Nonconforming Vital Area Barriers."

The following commitments were identified in this submittal:

- The openings for the cable tray wall penetrations between the Unit 1 and Unit 2 4 KV Rooms and the Unit 1 and 2 Reactor Cable Tunnels will be modified to ensure compliance with NUREG 0908. Compensatory measures will remain in place until the VA barriers are restored to conforming conditions.
- The ongoing Security Restart Readiness Self-Assessment team inspections will address the identification and correction of existing VA area barrier vulnerabilities due to design, materiel deficiencies or other causes prior to restart from the current outages of both units.
- Security will prepare and implement a procedure for future refueling outages to inspect VA barriers to identify and correct degraded and nonconforming conditions.

k] − 58

Sincerely.

A. Christopher Bakken, 11 Site Vice President

/mbd Attachment

- c: J. E. Dyer, Region III
 - R. P. Powers
 - P. A. Barrett
 - D. F. Kunsemiller
 - R. Whale
 - D. Hahn

Records Center, INPO NRC Resident Inspector

9906070042 99060; PDR ADOCK 05000315 PDR

了自动