

DMB

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

85-14

JUL 24 1985

Docket No. 50-315
Docket No. 50-316

American Electric Power Service
Corporation
Indiana and Michigan Electric Company
ATTN: Mr. John E. Dolan
Vice Chairman
1 Riverside Plaza
Columbus, OH 43216

Gentlemen:

Inspection Reports No. 50-315/315/85014(DRP) and No. 50-316/85014(DRP),
transmitted under cover letter dated June 6, 1985, contained a typographical
error.

Please replace page 9 of the inspection reports with a corrected Page 9
(attached) showing the section at the end of Section 5. to be: ...(Violation
314/85014-04; 316/85014-03).

Please accept our apologies for any inconvenience this action may have
caused.

Sincerely,

W D Shafer
W. D. Shafer, Chief
Reactor Projects Branch 2

Enclosure: Use Page 9 of report

cc w/encl:
W. G. Smith, Jr., Plant Manager
DMB/Document Control Desk (RIDS)
Resident Inspector, RIII
Ronald Callen, Michigan
Public Service Commission
EIS Coordinator, USEPA
Region 5 Office

8507110470 850702
PDR ADDCK 05000315
G PDR

IE 01

10-1-1



10-1-1