



11-11-11

SUPPLEMENT TO LER # 80-003/03L-0

SUPPLEMENT TO CAUSE DESCRIPTION

THE DETECTOR TUBE REPLACEMENT IS PART NUMBER 605519G01 MANUFACTURED
BY WESTINGHOUSE.

NO FURTHER ACTION IS PLANNED.



Handwritten scribbles in the top right corner.

Small vertical handwritten mark.

Small horizontal handwritten mark.