


JAN 2 1981

Docket No. 50-315
Docket No. 50-316

American Electric Power Service
Corporation
Indiana and Michigan Power Company
ATTN: Mr. John E. Dolan
Vice Chairman
Engineering
2 Broadway
New York, NY 10004




Gentlemen:

This refers to the routine inspection conducted by Messrs. E. Swanson and N. DuBry of this office on September 28 - October 31, 1980, of activities at the D. C. Cook Nuclear Plant, Units 1 and 2 authorized by NRC Operating License No. DPR-58 and No. DPR-74 and to the discussion of our findings with Mr. D. V. Shaller at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as described in the enclosed Appendix A, and a written response is required.

810 2250 429



American Electric Power Service
Corporation

- 2 -

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

R. F. Heishman, Chief
Reactor Operations and
Nuclear Support Branch

Enclosures:

1. Appendix A,
Notice of Violation
2. IE Inspection Reports
No. 50-315/80-15 and
No. 50-316/80-14

cc w/encl:

D. V. Shaller, Plant
Manager
Central Files
Reproduction Unit NRC 20b
AEOD
Resident Inspector, RIII
PDR
Local PDR
NSIC
TIC
Ronald Callen, Michigan
Public Service Commission

RIII

Swanson/jp
12/10/80

RIII

DuBry

RIII

Boyd

RIII

Heishman

12/31/80

