

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8104280446 DOC. DATE: 81/04/23 NOTARIZED: NO DOCKET #
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315
 AUTH. NAME: DELONG, S.D. AUTHOR AFFILIATION: Indiana & Michigan Electric Co.
 RECIP. NAME: RECIPIENT AFFILIATION: Region 3, Chicago, Office of the Director

SUBJECT: Updated LER 79-052/03X-1: on 791017, transmitter BLP 142 found to have drifted 7% high during investigation of high level indication for steam generator 4. Caused by bellows fill fluid leaking out due to burr on mounting beam.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+4
 TITLE: Incident Reports

NOTES: I&E: 3 copies all material.

05000315

ACTION:	RECIPIENT	COPIES	RECIPIENT		COPIES
	ID CODE/NAME		LTR	ENCL	
	VARGA, S. 04	3	3		
INTERNAL:	A/D COMP&STRU06	1	1	A/D ENV TECH 07	1 1
	A/D MATL & QU08	1	1	A/D OP REACT009	1 1
	A/D PLANT SYS10	1	1	A/D RAD PROT 11	1 1
	A/D SFTY ASSE12	1	1	ACC EVAL BR 14	1 1
	AEOD	3	3	AEOD/DMU	3 3
	ASLBP/J, HARD	1	1	AUX SYS BR 15	1 1
	CHEM ENG BR 16	1	1	CONT SYS BR 17	1 1
	CORE PERF BR 18	1	1	DIR, ENGINEERI20	1 1
	DIR, HUM FAC S21	1	1	DIR, SYS INTEG22	1 1
	EFF TR SYS BR23	1	1	EQUIP QUAL BR25	1 1
	GEOSCIENCES 26	1	1	I&C SYS BR 29	1 1
	I&E 05	1	1	JORDAN, E./IE	1 1
	LIC GUID BR 30	1	1	MATL ENG BR 32	1 1
	MECH ENG BR 33	1	1	NRC PDR 02	1 1
	OR ASSESS BR 35	1	1	POWER SYS BR 36	1 1
	RAD ASSESS BR39	1	1	REACT SYS BR 40	1 1
	REG FILE .01	1	1	REL & RISK A 41	1 1
	SFTY PROG EVA42	1	1	STRUCT ENG BR44	1 1
EXTERNAL:	ACRS 46	16	16	LPDR 03	1 1
	NSIC 05	1	1		

TOTAL NUMBER OF COPIES REQUIRED: LTR 64 ENCL 64

