

SEP 11 1985

Docket No. 50-315/85-13
Docket No. 50-316

American Electric Power Service
Corporation
Indiana and Michigan Electric Company
ATTN: Mr. John E. Dolan
Vice Chairman
Engineering and Construction
1 Riverside Plaza
Columbus, OH 43216

Gentlemen:

We recently transmitted to you Inspection Report Nos. 50-315/85013(DRS) and 50-316/85013(DRS) which contained minor typographical errors.

Please replace page 2 of the original cover letter with the attached page to this letter. Please contact me if you have any questions regarding this matter.

Sincerely,

Carl J. Paperiello, Director
Division of Reactor Safety

Enclosure: As stated

cc w/enclosure:
W. G. Smith, Jr., Plant Manager
DMB/Document Control Desk (RIDS)
Resident Inspector, RIII
Ronald Callen, Michigan
Public Service Commission
EIS Coordinator, USEPA
Region 5 Office
Nuclear Facilities and
Environmental Monitoring
Section

RIII *ms* RIII *Reyes* RIII *CP*
Guldmond/lc *d/c* Paperiello
9/8/85 *9/10*

8509160231 850911
PDR ADDOCK 05000315
G PDR

#E01 1/0

1/2 1/2
1/2 1/2
1/2 1/2



SEP 11 1985

As discussed in Paragraph 2.r of the enclosed report, it was identified that a difference of opinion exists between your staff and that of the NRC over your commitments relative to sealing certain fire barrier penetrations. In order to provide expeditious resolution of this issue, we understand that you will provide your position on this matter to the Region III Office two weeks following your receipt of this inspection report.

During the course of this inspection it was determined that a number of previously identified issues requiring action on your part and impacting your implementation of 10 CFR 50.48 and Appendix R remain open (Paragraphs 2.p, 2.t(16), 2.t(17), 2.t(10), 2.t(24), 2.t(25), 2.t(26), and 2.v). In addition, several new issues were identified which require action on your part and which impact your implementation of 10 CFR 50.48 and Appendix R (Paragraphs 4, 5.a, 6, 7, 8, and 9.d). These issues must be resolved consistent with your currently approved fire protection implementation schedule (two months following the 1985 Unit 2 refueling outage).

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosure will be placed in the NRC Public Document Room.

The response requested by this letter is not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



C. J. Paperiello, Director
Division of Reactor Safety

Enclosure: Inspection Report
Nos. 50-315/85013(DRS);
and 50-316/85013(DRS)

cc w/enclosure:
W. G. Smith, Jr., Plant Manager
DMB/Document Control Desk (RIDS)
Resident Inspector, RIII
Ronald Callen, Michigan
Public Service Commission
EIS Coordinator, USEPA
Region 5 Office
Nuclear Facilities and
Environmental Monitoring
Section

Handwritten scribbles and marks in the top right corner.

