

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8407310371 DOC. DATE: 84/07/27 NOTARIZED: NO DOCKET #
 FACIL: 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316
 AUTH. NAME AUTHOR AFFILIATION
 CHANDLER, J.C. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.)
 RECIP. NAME RECIPIENT AFFILIATION
 DENTON, H.R. Office of Nuclear Reactor Regulation, Director

SUBJECT: Forwards proprietary Rev 2 to XN-NF-84-21 (P), "DC Cook Unit 2, Cycle 5 5% Steam Generator Tube Plugging Limiting Break LOCA/ECCS Analysis," per American Electric Power Svc Co request, Rept withheld (ref 10CFR2.790).

SEE SUBJECT'S FILES FOR REPT.

DISTRIBUTION CODE: PA01S COPIES RECEIVED: LTR 1 ENCL 4 SIZE: 1+76
 TITLE: Proprietary Review Distribution-Operating Reactor

NOTES:

05000316

OL: 12/23/72

	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTR	ENCL		LTR	ENCL
	NRR ORB1 BC	7	7			
		<i>#2 thru #8</i>				
INTERNAL:	ELD/HDS3	1	0	REG FILE	1	1
	RGN3	1	1			
		<i>#9</i>				
EXTERNAL:	ACRS	6	6	LPDR	1	0
	NRC PDR	1	0	NTIS	1	0
		<i>#10 thru #15</i>				

Extra Cys.

To: D. Wiggington

DRB #1 #16 thru #41

THE
UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
WASHINGTON, D. C. 20240

MEMORANDUM FOR THE DIRECTOR, BUREAU OF LAND MANAGEMENT
FROM: SAC, DENVER
SUBJECT: [Illegible]

[Illegible text follows]

[Illegible text follows]

[Illegible text follows]

[Illegible text follows]

EXXON NUCLEAR COMPANY, Inc.

2101 Horn Rapids Road
P. O. Box 130, Richland, Washington 99352
Phone: (509) 375-8100 Telex: 15-2878

July 27, 1984
JCC:106:84

Donald C. Cook Nuclear Plant Unit No. 2
Docket No. 50-316
License No. DPR-74
SUPPORTING DOCUMENTATION FOR UNIT 2 TECHNICAL SPECIFICATION CHANGES FOR CYCLE
5 RELOAD

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Bethesda, MD 20014

Ref.: Letter, J.C. Chandler (ENC) to H.R. Denton (USNRC), "Supporting
Documentation for Unit 2 Technical Specification Changes for cycle
5 Reload," (JCC:040:84), dated March 2, 1984.

Dear Mr. Denton:

Enclosed are forty-one copies of Revision 2 to XN-NF-84-21(P), "Donald
C. Cook Unit 2 Cycle 5 5% Steam Generator Tube Plugging Limiting Break
LOCA/ECCS Analysis." At the request of American Electric Power Service
Company (AEPSC), this report is being transmitted directly by Exxon Nuclear.

Exxon Nuclear Company considers information contained in the enclosed
report to be proprietary. In accordance with the Commission's Regulation 10
CFR 2.790(b), the Affidavit enclosed with the reference letter provides the
necessary information to support the withholding of this response from public
dis closure.

If you have any questions about this submission, please contact Mr. James
G. Feinstein of AEPSC at (614) 223-2040.


Sincerely,



J. C. Chandler, Lead Engineer
Reload Fuel Licensing

naa

cc: Mr. D. L. Wigginton (USNRC)
Mr. M. P. Alexich (AEPSC)



*PA01
1/1A1*
*Extra Cys
To: D. Wigginton
DR#1*

20