MAR 25 1986

UME

11 TE01

Docket No. 50-315/86-04 Docket No. 50-316

American Electric Power Service Corporation Indiana and Michigan Electric Company ATTN: Mr. John E. Dolan Vice Chairman 1 Riverside Plaza Columbus, OH 43216

Gentlemen:

This refers to the routine safety inspection conducted by B. L. Jorgensen, J. K. Heller, C. L. Wolfsen and E. R. Swanson, of this office on January 21, 1986 through February 18, 1986, of activities at the Donald C. Cook Nuclear Plant, Units 1 and 2 authorized by NRC Operating Licenses No. DPR-58 and No. DPR-74 and to the discussion of our findings with W. G. Smith, Jr., and others of your staff during the course of and at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice. With respect to item Number 1 the inspection showed that action had been taken to correct the identified violation and to prevent recurrence. Our understanding of your corrective actions is described in Paragraph 2.c of the enclosed inspection report. Consequently, no reply to this violation is required and we have no further questions regarding this matter at this time.

Regarding the remaining item, a written response is required.

As described in Paragraph 2.a. of the enclosed inspection report, we have determined certain other of your activities also appeared to be in violation of NRC requirements. A Notice of Violation concerning these items is not being issued at this time pending further evaluation by this office concerning appropriate enforcement action on the matter. You will be notified in subsequent correspondence concerning resolution of these items.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosures, and your response to this letter will be placed in the NRC Public Document Room.



*

•

ne transfer to be been to be a second to be a secon

• •

• ·

American Electric Power Service Corporation 2

The response directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

g Frei in British

W. G. Guldemond, Chief

Reactor Projects Branch 2

Enclosures:

- 1. Notice of Violation
- 2. Inspection Reports
 No. 50-315/86004(DRP);
 No. 50-316/86004(DRP)



cc w/enclosures: W. G. Smith, Jr., Plant Manager DCS/RSB (RIDS) Licensing Fee Management Branch Resident Inspector, RIII Ronald Callen, Michigan Public Service Commission EIS Coordinator, USEPA Region 5 Office Nuclear Facilities and Environmental Monitoring Section

RIII Suermann/bls 3(25

3



RIII Guldemond



4 .

•. -

0

•