

APPENDIX

SALP BOARD REPORT

---

U. S. NUCLEAR REGULATORY COMMISSION

REGION III

---

SYSTEMATIC ASSESSMENT OF LICENSEE PERFORMANCE

50-315/88001; 50-316/88001  
Inspection Report No.

Indiana Michigan Power Company  
Name of Licensee

Donald C. Cook Units 1 and 2  
Name of Facility

October 1, 1986 through February 29, 1988  
Assessment Period

8807280223 880718  
PDR ADOCK 05000315  
Q PDC

Donald C. Cook Facility

A. Summary of Meeting with Indiana Michigan Power Company on June 6, 1988

The findings and conclusions of the SALP Board are documented in Report No. 50-315/88001; 50-316/88001 and were discussed with the licensee on June 6, 1988, at the D. C. Cook facility.

While the meeting was primarily a discussion between the licensee and NRC, it was open to members of the public as observers.

The following licensee and NRC personnel were in attendance.

Indiana Michigan Power Company

D. H. Williams, Jr., Senior Executive Vice President - Engineer  
and Construction  
M. P. Alexich, Vice President - Nuclear Operations  
H. N. Scherer, Jr., Senior Executive Vice President - Electrical Engineering  
S. J. Brewer, Manager - Nuclear Safety and Licensing  
P. A. Barrett, Director - Quality Assurance  
W. G. Smith, Plant Manager  
A. D. Blind, Assistant Plant Manager  
J. Rutkowski, Assistant Plant Manager  
L. S. Gibson, Assistant Plant Manager

Independent Nuclear Consultant

Herbert Isbin

Nuclear Regulatory Commission

C. J. Paperiello, Deputy Regional Administrator  
W. L. Axelson, Chief, Projects Branch 2, DRP  
B. L. Burgess, Chief, Projects Section 2A, DRP  
R. Kazmar, Project Inspector, Reactor Projects Branch 2A  
B. L. Jorgensen, Senior Resident Inspector, D. C. Cook  
J. K. Heller, Resident Inspector, D. C. Cook

Nuclear Reactor Regulation (NRR)

J. Stang, Project Manager, NRR