

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8909210144 DOC.DATE: 89/09/08 NOTARIZED: NO DOCKET #
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316

AUTH.NAME AUTHOR AFFILIATION
 SMITH, W.G. Indiana Michigan Power Co.
 RECIPIENT NAME RECIPIENT AFFILIATION
 DAVIS, A.B. Document Control Branch (Document Control Desk)

SUBJECT: Special rept: on 890908, fire suppression water sys inoperable per Tech Spec 3.7.9.1.b due to fire protection isolation.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD3-1 LA	1	PD3-1 PD	1
	GIITTER, J.	1		
INTERNAL:	ACRS MICHELSON	1	ACRS MOELLER	2
	ACRS WYLIE	1	AEOD/DOA	1
	AEOD/DSP/TPAB	1	AEOD/ROAB/DSP	2
	DEDRO	1	IRM/DCTS/DAB	1
	NRR/DEST/CEB 8H	1	NRR/DEST/ESB 8D	1
	NRR/DEST/ICSB 7	1	NRR/DEST/MEB 9H	1
	NRR/DEST/MTB 9H	1	NRR/DEST/PSB 8D	1
	NRR/DEST/RSB 8E	1	NRR/DEST/SGB 8D	1
	NRR/DLPQ/HFB 10	1	NRR/DLPQ/PEB 10	1
	NRR/DOEA/EAB 11	1	NRR/DRREP/RPB 10	2
	NUDOCS-ABSTRACT	1	<u>REG FILE</u> 02	1
	RES/DSIR/EIB	1	RGN3 FILE 01	1
EXTERNAL:	EG&G WILLIAMS, S	4	L ST LOBBY WARD	1
	LPDR	1	NRC PDR	1
	NSIC MAYS, G	1	NSIC MURPHY, G.A	1
	NUDOCS FULL TXT	1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

R
I
D
S
/
A
D
S
/
A
D
S
/
A
D
S

Indiana Michigan
Power Company
Cook Nuclear Plant
P.O. Box 458
Bridgman, MI 49106
616 465 5901



September 8, 1989

Donald C. Cook Nuclear Plant Unit Nos. 1 and 2
Docket Nos. 50-315 and 50-316
License Nos. DPR-58 and DPR-74

U.S. Nuclear Regulatory Commission
Document Control
One White Flint North
11555 Rockville Pike
Rockville, Maryland 20852

Attn: A.B. Davis


Dear Mr. Davis:

This is to confirm a verbal report made to Mr. Joe Ulie of your staff at 1110 hours on September 8, 1989. At that time, Mr. Ulie was informed that the Fire Suppression Water System was not operable as required by Technical Specification 3.7.9.1.b due to the planned isolation of a portion of the east and south legs of the outside fire protection ring header. This isolation was required to facilitate the replacement of valve 12-FP-133 in the outside ring header. The replacement of valve 12-FP-133 is expected to be completed within 14 days and the Fire Protection System returned to service by September 21, 1989.

One fire hydrant in the protected area and one fire hydrant outside the protected area were removed from service due to the isolation of this section of the Fire Protection System. Backup fire protection is available from adjacent fire hydrants and the plant fire truck.

This letter will fulfill the requirements of Technical Specification 3.7.9.1 action b.2b which required a followup report no later than the next working day following the event and Technical Specification 3.7.9.1 action b.2c that requires a followup report within 14 days.

Respectfully,


W. G. Smith, Jr.
Plant Manager

8909210144 890908
PDR ADOCK 05000315
S PNU

WGS:clw

cc: see attached list

IE22
10

cc: D.H. Williams, Jr.
A.B. Davis, Region III
M.P. Alexich
P.A. Barrett
J.E. Borggren
R.F. Kroeger
NRC Resident Inspector
J.G. Giitter, NRC
R.C. Callen
G. Charnoff, Esq.
Dottie Sherman, ANI Library
D. Hahn
INPO
PNSRC
A.A. Blind
S.J. Brewer/B.P. Lauzau