

SEP 6 1990

Docket No. 50-315
Docket No. 50-316

Indiana Michigan Power Company
ATTN: Mr. Milton P. Alexich
Vice President
Nuclear Operations Division
1 Riverside Plaza
Columbus, OH 43216

Gentlemen:

This refers to the routine safety inspection conducted by Mr. K. D. Ward of this office on July 11 through August 29, 1990, of activities related to inservice inspection, licensee action on previous inspection findings, and on incore thimble tube thinning at the D. C. Cook Nuclear Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-58 and No. DPR-74, and to the discussion of our findings with Mr. J. Droste at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Mark A. Ring, Chief
Engineering Branch

Enclosure: Inspection
Reports No. 50-315/90015(DRS);
No. 50-316/90015(DRS)

See Attached Distribution

RIII
WJ
Ward/jk
09/04/90

RIII
BAB
Burgess
09/06/90

RIII
SD
Danielson
09/06/90

RIII
MR
Ring
09/06/90

9009120165 900906
PDR ADDOCK 05000315
Q PNU

11
LE01

Indiana Michigan Power Company

2

SEP 6 1990

Distribution

cc w/enclosure:

A. A. Blind, Plant Manager

DCD/DCB (RIDS)

OC/LFDCB

Resident Inspector, RIII

James R. Padgett, Michigan Public

Service Commission

EIS Coordinator, USEPA

Region 5 Office

Michigan Department of

Public Health

D. C. Cook, LPM, NRR