

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9010030001      DOC. DATE: 90/09/21      NOTARIZED: NO      DOCKET #  
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315  
       50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316  
 AUTH. NAME                      AUTHOR AFFILIATION  
 ALEXICH, M.P.                  American Electric Power Service Corp.  
 RECIP. NAME                    RECIPIENT AFFILIATION  
 MURLEY, T.E.                    Document Control Branch (Document Control Desk)

SUBJECT: Submits rept on action items status, per NRC Bulletin 88-010 re molded-case circuit breakers.

DISTRIBUTION CODE: IE21D      COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2  
 TITLE: Bulletin Response 88-10 - Nonconforming Molded Case Circuit Breakers.

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTR	ENCL		ID CODE/NAME		LTR	ENCL
	PD3-1 LA		1	0		PD3-1 PD		1	1
	COLBURN, T.		1	1					
INTERNAL:	AEOD/DOA		1	1	AEOD/DSP/TPAB		1	1	
	NRR DOEA/GCB 11		1	1	NRR GILL, A.S.		1	1	
	NRR STONE, J.C.		1	1	NRR/DET/EMEB 7E		1	1	
	NRR/DOEA/OEAB11		1	1	NRR/DOEA/OGCB11		1	1	
	NRR/DREP/PEPB9D		1	1	NRR/DST 8E2		1	1	
	NRR/DMAS/ILRB12		1	1	NRR/POTAPOVS, U		1	1	
	<u>REG FILE</u> 02		1	1	RES/DSIR/EIB		1	1	
	RGN3 FILE 01		1	1					
EXTERNAL:	NRC PDR		1	1	NSIC		1	1	

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 20 ENCL 19

R  
I  
D  
S  
/  
A  
D  
S  
/  
A  
D  
D  
S

American Electric  
Service Corporation  
1 Riverside Plaza  
Columbus, OH 43215  
614 223 1000



**AMERICAN  
ELECTRIC  
POWER**

AEP:NRC:1083F

Donald C. Cook Nuclear Plant  
Docket Nos. 50-315 and 50-316  
License Nos. DPR-58 and DPR-74  
NRC BULLETIN NO. 88-10: REPORT ON ACTION ITEM STATUS

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D. C. 20555

Attn: T. E. Murley

September 21, 1990

Dear Dr. Murley:

The purpose of this letter is to respond to a letter dated July 25, 1990 written by Mr. T. M. Colburn of your staff on the subject of molded-case circuit breakers. In that letter, Mr. Colburn stated that, based upon review of our submittals AEP:NRC:1083A and AEP:NRC:1083B, dated May 16, 1989 and July 27, 1989, respectively, the "staff understands that all actions are to have been completed by this time."

In order to avoid any misunderstanding in this matter, we must note that in our letter AEP:NRC:1083A, we identified 100 installed circuit breakers whose traceability to the manufacturer had not been established. We committed to replace at least one-half of these prior to the startup from the 1989 Unit 1 refueling outage, which was in progress at the time of that submittal, and to replace any remaining untraceable Unit 1 circuit breakers before startup from the 1990 Unit 1 refueling outage, which is scheduled to begin in October of this year.

In addition, we noted in our letter AEP:NRC:1083B that there were 36 molded-case circuit breakers installed in Unit 2 that could not be traced to the circuit breaker manufacturer. As stated in that letter, we elected to replace 32 Westinghouse circuit breakers prior to the Unit 2 1990 refueling outage and committed to replace the remaining four General Electric circuit breakers "before startup from the 1990 refueling outage." Following this schedule, we have replaced all 36 circuit breakers.

9010030001 900921  
PDR ADDCK 05000315  
R PDC

IEZ/  
1/0



Dr. T. E. Murley


-2-

AEP:NRC:1083F

Our replacement schedule for these circuit breakers is consistent with the requirements of IE Bulletin 88-10 and the commitments we have made in our responses to the Bulletin since we intend to have all untraceable breakers replaced before startup from each unit's 1990 refueling outage.

This document has been prepared following Corporate procedures that incorporate a reasonable set of controls to ensure its accuracy and completeness prior to signature by the undersigned.

Sincerely,



M. P. Alexich  
Vice President

MPA/eh

cc: D. H. Williams, Jr.  
A. A. Blind - Bridgman  
J. R. Padgett  
G. Charnoff  
NFEM Section Chief  
A. B. Davis - Region III  
NRC Resident Inspector - Bridgman

00013