

JAN 6 8 1991

Dr. D. PCB7  
Rid S.

Docket No. 50-315/90-25  
No. 50-316

American Electric Power Service  
Corporation  
Indiana Michigan Power Company  
ATTN: Mr. M. P. Alexich  
Vice President - Nuclear  
Operations Division  
1 Riverside Plaza  
Columbus, OH 43216

Gentlemen:

This refers to the routine safety inspection conducted by Messrs. J. A. Isom and D. G. Passehl of this office from November 14, through December 21, 1990, of activities at the Donald C. Cook Nuclear Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-58 and DPR-74. This also refers to the discussion of our findings with Mr. A. A. Blind and others of your staff at the conclusion of the inspection.


The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



Brent Clayton, Chief  
Reactor Projects Branch 2

Enclosure:

1. Inspection Report  
No. 50-315/90025(DRP);  
No. 50-316/90025(DRP)

See Attached Distribution

9101150024 910108  
PDR ADDCK 05000315  
Q PDR

IE01  
41

JAN 08 1991

American Electric Power Service  
Corporation

2

Distribution

cc w/enclosures:

A. A. Blind, Plant Manager

DCD/DCB (RIDS)

Licensing Fee Management Branch

Resident Inspector, RIII

James R. Padgett, Michigan

Public Service Commission

EIS Coordinator, USEPA

Region 5 Office

Michigan Department of

Public Health

T. Colburn, LPM, NRR

YES

RIII *EAS*

Schweibinz

01-07-91

RIII

*J*  
Jorgensen

1-7-91

RIII

*RWA*  
for Clayton

1/8/91



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION III  
799 ROOSEVELT ROAD  
GLEN ELLYN, ILLINOIS 60137

JAN 01 1991

Docket No. 50-315  
No. 50-316

American Electric Power Service  
Corporation  
Indiana Michigan Power Company  
ATTN: Mr. M. P. Alexich  
Vice President - Nuclear  
Operations Division  
1 Riverside Plaza  
Columbus, OH 43216

Gentlemen:

This refers to the routine safety inspection conducted by Messrs. J. A. Isom and D. G. Passehl of this office from November 14, through December 21, 1990, of activities at the Donald C. Cook Nuclear Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-58 and DPR-74. This also refers to the discussion of our findings with Mr. A. A. Blind and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

*Robert W. McJannet*

*for* Brent Clayton, Chief  
Reactor Projects Branch 2

Enclosure:

1. Inspection Report  
No. 50-315/90025(DRP);  
No. 50-316/90025(DRP)

See Attached Distribution



JAN 08 1981

American Electric Power Service  
Corporation

2

Distribution

cc w/enclosures:

A. A. Blind, Plant Manager

DCD/DCB (RIDS)

Licensing Fee Management Branch

Resident Inspector, RIII

James R. Padgett, Michigan

Public Service Commission

EIS Coordinator, USEPA

Region 5 Office

Michigan Department of

Public Health

T. Colburn, LPM, NRR

