

LICENSEE EVENT REPORT

CONTROL BLOCK:                               (1) PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION

(01) F I L I S I S I (2) 0101-10101010101-1010 (3) 4177 1777 (4) 1 (5)

CCN'T 011 REPORT SOURCE (6) L (7) 1015101010131315 (8) 10151114811 (9) 0161151811 (10)

(11) While operating at 100% power, Area Radiation Monitoring System channel 7, Fuel Handling Building, was discovered to have the alarm set point of >15MR/HR. Action was initiated in accordance with T.S. 3.3.3.1 and the set point was restored to ≤15 MR/HR. This is the first occurrence of this type. There was no adverse affect on the health or safety of the public. No fuel handling evolutions occurred between the time of the last functional check and the discovery of the high setpoint.

(019) RIA (11) XI (12) ZI (13) ZIZIZIZIZI (14) ZI (15) ZI (16) (17) 81 (18) 0124 (19) 1013 (20) L (21) 010610 (22) N (23) N (24) ZI (25) Z19199 (26)

(27) The cause for ARMS channel 7 alarm set point >15 MR /HR could not be determined. The setpoint was restored to ≤15MR/HR. No further action is considered necessary.

(115) E (31) 11010 (32) NA (33) A (34) Operator Observation (35)

(116) Z (36) Z (37) NA (38) NA (39)

(117) 000 (40) Z (41) NA (42)

(118) 000 (43) NA (44)

(119) Z (45) NA (46)

(212) Z (47) NA (48)

NAME OF PREPARER P. L. Pace PHONE (305) 552-3801