

92-02
1111 (B)

MAR

Docket No. 50-315
Docket No. 50-316

Indiana Michigan Power Company
ATTN: Mr. E. E. Fitzpatrick
Vice President
Nuclear Operations Division
1 Riverside Plaza
Columbus, OH 43216

Dear Mr. Fitzpatrick:

This refers to the routine safety inspection conducted by J. A. Isom and D. G. Passehl of this office on January 8 through February 18, 1992, of activities at the Donald C. Cook Nuclear Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-58 and DPR-74, and to the discussion of our findings with A. A. Blind and others of your staff at the conclusion of the inspection.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

No violations of NRC requirements were identified during the course of this inspection. One unresolved item was identified concerning the operability of the Emergency Diesel Generators in the past with degraded room ventilation airflows.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

W. D. Shafer, Chief
Reactor Projects Branch 2

Enclosure:
Inspection Reports
No. 50-315/92002(DRP);
No. 50-316/92002(DRP)

See Attached Distribution

RIII *YES*
EAS
Schweibinz
3-6-92


YES
RIII
EAS
for Jorgensen
3-6-92

RIII
W
Shafer
3-6-92

TEU

9203120199 920306
PDR ADOCK 05000315
Q PDR





UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

MAK

Docket No. 50-315
Docket No. 50-316

Indiana Michigan Power Company
ATTN: Mr. E. E. Fitzpatrick
Vice President
Nuclear Operations Division
1 Riverside Plaza
Columbus, OH 43216

Dear Mr. Fitzpatrick:

This refers to the routine safety inspection conducted by J. A. Isom and D. G. Passehl of this office on January 8 through February 18, 1992, of activities at the Donald C. Cook Nuclear Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-58 and DPR-74, and to the discussion of our findings with A. A. Blind and others of your staff at the conclusion of the inspection.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

No violations of NRC requirements were identified during the course of this inspection. One unresolved item was identified concerning the operability of the Emergency Diesel Generators in the past with degraded room ventilation airflows.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

W. D. Shafer, Chief
Reactor Projects Branch 2

Enclosure:
Inspection Reports
No. 50-315/92002(DRP);
No. 50-316/92002(DRP)

See Attached Distribution



Indiana Michigan Power Company

2

Distribution

cc w/enclosures:

A. A. Blind, Plant Manager

DCD/DCB (RIDS)

OC/LFDCB

Resident Inspector, RIII

James R. Padgett, Michigan

Public Service Commission

EIS Coordinator, USEPA

Region 5 Office

Michigan Department of

Public Health

D. C. Cook, LPM, NRR