



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

TIC

MAY 5 1980

Docket No. 50-315
Docket No. 50-316

American Electric Power Service
Corporation
Indiana and Michigan Power Company
ATTN: Mr. John E. Dolan, Vice Chairman
Engineering and Construction
2 Broadway
New York, NY 10004

Gentlemen:

This refers to the inspection conducted by Messrs. I. N. Jackiw, J. F. Streeter, E. R. Swanson, L. G. McGregor and R. E. Masse of this office on January 14-18, 21-5 and February 11-12, 1980 at the D. C. Cook Nuclear Plant Units 1 and 2 and on January 29-31 and March 3-5, 1980 at the AEPSC Corporate Office, of activities authorized by NRC Operating License No. DPR-58 and DPR-74 and to the discussions of our findings with Mr. D. Shaller and other at the conclusion of the inspection. This also refers to the meeting held at the Nuclear Regulatory Commission's Offices in Glen Ellyn, Illinois on April 15, 1980 and attended by Mr. J. G. Keppler and members of his staff and Mr. J. E. Dolan and members of his staff.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in noncompliance with NRC requirements, as described in the enclosed Appendix A.

This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office within twenty days of your receipt of this notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved.

As discussed with you this was a special inspection to review the effectiveness of your QA program in selected areas for both past and ongoing activities. While the items of noncompliance identified during this inspection taken individually, are not considered significant the number of examples indicate that further management attention in these areas is needed. We will continue to review the effectiveness of your QA program during future inspections.

60


Q 8007220 095:

MAY 5 1980

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC's Public Document Room, except as follows. If the enclosures contain information that you or your contractors believe to be proprietary, you must apply in writing to this office, within twenty days of your receipt of this letter, to withhold such information from public disclosure. The application must include a full statement of the reasons for which the information is considered proprietary, and should be prepared so that proprietary information identified in the application is contained in an enclosure to the application.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



R. F. Heishman, Chief
Reactor Operations and Nuclear
Support Branch

Enclosures:

1. Appendix A, Notice
of Violation
2. IE Inspection Report
No. 50-315/80-01 and
No. 50-316/80-01

cc w/encls:

Mr. D. V. Shaller, Plant
Manager
Central Files
Reproduction Unit NRC 20b
PDR
Local PDR
NSIC
TIC
Ronald Callen, Michigan Public
Service Commission