

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9308250287 DOC.DATE: 93/08/17 NOTARIZED: NO DOCKET #
 FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana M 05000316
 AUTH.NAME AUTHOR AFFILIATION
 SHAFER,W.D. Region 3 (Post 820201)
 RECIP.NAME RECIPIENT AFFILIATION
 FITZPATRICK,E. Indiana Michigan Power Co.

SUBJECT: Forwards insp repts 50-315/93-16 & 50-316/93-16 on
 930616-0727 & NOV.Concern reinforced due to prolonged
 inaction to repair minor leak.

DISTRIBUTION CODE: IE01D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 3+21
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTR	ENCL		ID CODE/NAME		LTR	ENCL
	PD3-1	PD	1	1		DEAN,W		1	1
INTERNAL:	AEOD/DEIB		1	1		AEOD/DSP/ROAB		1	1
	AEOD/DSP/TPAB		1	1		AEOD/TTC		1	1
	DEDRO		1	1		NRR/DORS/OEAB		1	1
	NRR/DRCH/HHFB		1	1		NRR/DRIL/RPEB		1	1
	NRR/DRSS/PEPB		1	1		NRR/PMAS/ILPB1		1	1
	NRR/PMAS/ILPB2		1	1		NUDOCS-ABSTRACT		1	1
	OE DIR		1	1		OGC/HDS2		1	1
	REG FILE 02		1	1		RES/HFB		1	1
	RGN3 FILE 01		1	1					
EXTERNAL:	EG&G/BRYCE,J.H.		1	1		NRC PDR		1	1
	NSIC		1	1					

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK.
 ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 22 ENCL 22



UNITED STATES
 NUCLEAR REGULATORY COMMISSION
 REGION III
 799 ROOSEVELT ROAD
 GLEN ELLYN, ILLINOIS 60137

AUG 17 1993

Docket No. 50-315
 Docket No. 50-316

Indiana Michigan Power Company
 ATTN: Mr. E. E. Fitzpatrick
 Vice President
 1 Riverside Plaza
 Columbus, OH 43216

Dear Mr. Fitzpatrick:

This refers to the routine safety inspection conducted by J. A. Isom, D. J. Hartland, and T. Tella of this office on June 16 through July 27, 1993, of activities at the Donald C. Cook Nuclear Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-58 and DPR-74, and to the discussion of our findings with A. A. Blind and others of your staff at the conclusion of the inspection.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Based on the results of this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice of Violation (Notice). The violation regarding your failure to perform a formal safety evaluation prior to de-energizing in the open position an Emergency Diesel Generator (EDG) room ventilation damper is a concern because it ultimately contributed to the inoperability of the EDG. In addition, this deficiency was not identified during your investigation into this event.

The violation regarding the Unit 2 East Motor-Driven Auxiliary Feedwater (MDAFW) pump is of concern because your failure to repair a "minor" pump packing leak in a reasonable time eventually lead to a condition where the leak worsened and caused your East MDAFW pump outer bearing to be seriously degraded. Our concern is reinforced by the fact that prolonged inaction to repair a "minor" emergency diesel lube oil leak in mid-1992 eventually led to inoperability of the diesel. This was the subject of escalated enforcement action.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific actions taken and any additional actions you plan to prevent recurrence. You are specifically requested to address actions you plan to take to ensure that maintenance on safety-related equipment is not improperly deferred, such that the equipment is seriously degraded or rendered inoperable. After reviewing your response to the Notice,

9308250287 930817
 PDR ADOCK 05000315
 G PDR

JE01
 1/1

AUG 17 1993

Public

Indiana Michigan Power Company

2


including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosures, and your responses to this letter will be placed in the NRC Public Document Room.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



W. D. Shafer, Chief
Reactor Projects Branch 2

Enclosures:


- 1. Notice of Violation
- 2. Inspection Reports
 - No. 50-315/93016(DRP);
 - No. 50-316/93016(DRP)


cc w/enclosure:

A. A. Blind, Plant Manager
 OC/LFDCB
 Resident Inspector, RIII
 James R. Padgett, Michigan Public
 Service Commission
 EIS Coordinator, USEPA
 Region 5 Office
 Michigan Department of
 Public Health
 D. C. Cook, LPM, NRR

bcc "Public"

RIII
EAS
 Schweibinz
 8-17-93

RIII

 Jorgensen
 8-17-93

RIII
HA 2 por

 JABLONSKI
 (para. 5)

RIII

 Pirok

RIII

 Shafer

24018

IEO1
11

AUG 17 1993

Indiana Michigan Power Company

2


including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosures, and your responses to this letter will be placed in the NRC Public Document Room.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



W. D. Shafer, Chief
Reactor Projects Branch 2

Enclosures:

1. Notice of Violation
2. Inspection Reports
 No. 50-315/93016(DRP);
 No. 50-316/93016(DRP)

cc w/enclosure:

A. A. Blind, Plant Manager
OC/LFDCB
Resident Inspector, RIII
James R. Padgett, Michigan Public
Service Commission
EIS Coordinator, USEPA
Region 5 Office
Michigan Department of
Public Health
D. C. Cook, LPM, NRR