

December 3, 1993

Docket Nos. 50-315
and 50-316

DISTRIBUTION

Docket File
NRC & LPDRs
J. Roe
J. Zwolinski
J. Hickman
C. Jamerson

R. Barrett
OGC
ACRS (10)
B. Jorgensen, RIII
A. R. Blough

Mr. E. E. Fitzpatrick, Vice President
Indiana Michigan Power Company
c/o American Electric Power Service Corporation
1 Riverside Plaza
Columbus, Ohio 43215

Dear Mr. Fitzpatrick:

SUBJECT: DONALD C. COOK NUCLEAR PLANT, UNIT NOS. 1 AND 2 - RESPONSE TO NRC
BULLETIN 93-02, "DEBRIS PLUGGING OF EMERGENCY CORE COOLING SUCTION
STRAINERS" (TAC NO. M86550)

This letter acknowledges receipt of your responses dated June 11, 1993, and August 6, 1993, to NRC Bulletin 93-02 (Bulletin). The Bulletin was issued May 11, 1993, to all nuclear power reactor licensees. It requested licensees to identify fibrous material in the primary containment, take any necessary compensatory measures, and remove any such material. Your response stated that fibrous filter material, such as described in the Bulletin, was identified as being used in your containment, that the material as configured would remain confined in the event of a LOCA; however, the material has been removed from Unit 2 and will be removed from Unit 1 during the next outage of sufficient duration. Based on the above response, we consider your actions and commitments to be acceptable. Please retain any records of your actions in response to this Bulletin, as subsequent inspection activities may be conducted in regards to this issue.

Should you have any questions, please contact me at (301) 504-3017.

Sincerely,

Original Signed By:

John B. Hickman, Project Manager
Project Directorate III-1
Division of Reactor Projects - III/IV/V
Office of Nuclear Reactor Regulation

060102

cc: see next page

OFFICE	LA:PD31	PM:PD31	(A)D:PD31
NAME	CJamerson	JHickman:jkd	ARBlough
DATE	12/3/93	12/3/93	12/3/93

OFFICIAL RECORD COPY FILENAME: G:\WPDOCS\DCCOOK\C086550.LTR

9312130273 931203
PDR ADDCK 05000315
Q PDR

NRC FILE CENTER COPY

DF01 1/0
NO



6-1

6-1



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

December 3, 1993

Docket Nos. 50-315
and 50-316

Mr. E. E. Fitzpatrick, Vice President
Indiana Michigan Power Company
c/o American Electric Power Service Corporation
1 Riverside Plaza
Columbus, Ohio 43215

Dear Mr. Fitzpatrick:

SUBJECT: DONALD C. COOK NUCLEAR PLANT, UNIT NOS. 1 AND 2 - RESPONSE TO NRC
BULLETIN 93-02, "DEBRIS PLUGGING OF EMERGENCY CORE COOLING SUCTION
STRAINERS" (TAC NO. M86550)

This letter acknowledges receipt of your responses dated June 11, 1993, and August 6, 1993, to NRC Bulletin 93-02 (Bulletin). The Bulletin was issued May 11, 1993, to all nuclear power reactor licensees. It requested licensees to identify fibrous material in the primary containment, take any necessary compensatory measures, and remove any such material. Your response stated that fibrous filter material, such as described in the Bulletin, was identified as being used in your containment, that the material as configured would remain confined in the event of a LOCA; however, the material has been removed from Unit 2 and will be removed from Unit 1 during the next outage of sufficient duration. Based on the above response, we consider your actions and commitments to be acceptable. Please retain any records of your actions in response to this Bulletin, as subsequent inspection activities may be conducted in regards to this issue.


Should you have any questions, please contact me at (301) 504-3017.

Sincerely,

A handwritten signature in cursive script, appearing to read "John B. Hickman".

John B. Hickman, Project Manager
Project Directorate III-1
Division of Reactor Projects - III/IV/V
Office of Nuclear Reactor Regulation

cc: see next page



Mr. E. E. Fitzpatrick
Indiana Michigan Power Company

Donald C. Cook Nuclear Plant

cc:

Regional Administrator, Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Mr. S. Brewer
American Electric Power Service
Corporation
1 Riverside Plaza
Columbus, Ohio 43215

Attorney General
Department of Attorney General
525 West Ottawa Street
Lansing, Michigan 48913

Township Supervisor
Lake Township Hall
Post Office Box 818
Bridgman, Michigan 49106

Al Blind, Plant Manager
Donald C. Cook Nuclear Plant
Post Office Box 458
Bridgman, Michigan 49106

U.S. Nuclear Regulatory Commission
Resident Inspector Office
7700 Red Arrow Highway
Stevensville, Michigan 49127

Gerald Charnoff, Esquire
Shaw, Pittman, Potts and Trowbridge
2300 N Street, N. W.
Washington, DC 20037

Mayor, City of Bridgman
Post Office Box 366
Bridgman, Michigan 49106

Special Assistant to the Governor
Room 1 - State Capitol
Lansing, Michigan 48909

Nuclear Facilities and Environmental
Monitoring Section Office
Division of Radiological Health
Department of Public Health
3423 N. Logan Street
P. O. Box 30195
Lansing, Michigan 48909

