

FORD 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9402160111 DOC. DATE: 94/02/07 NOTARIZED: NO DOCKET #
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana M 05000316
 AUTH. NAME AUTHOR AFFILIATION
 KROPP, W.J. Region 3 (Post 820201)
 RECIP. NAME RECIPIENT AFFILIATION
 FITZPATRICK, E. Indiana Michigan Power Co.

SUBJECT: Forwards insp repts 50-315/93-24 & 50-325/93-24 on 931208-940118. No violations noted.

DISTRIBUTION CODE: IE01D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2+6
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:


RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD3-1 PD	1 1	HICKMAN, J	1 1
INTERNAL: AEOD/DEIB	1 1	AEOD/DSP/ROAB	1 1
AEOD/DSP/TPAB	1 1	AEOD/TTC	1 1
DEDRO	1 1	NRR/DORS/OEAB	1 1
NRR/DRCH/HHFB	1 1	NRR/DRIL/RPEB	1 1
NRR/DRSS/PEPB	1 1	NRR/PMAS/ILPB1	1 1
NRR/PMAS/ILPB2	1 1	NUDOCS-ABSTRACT	1 1
<u>OE-DIR</u>	1 1	OGC/HDS2	1 1
<u>REG. FILE</u> 02	1 1	RES/HFB	1 1
RGN3 FILE 01	1 1		
EXTERNAL: EG&G/BRYCE, J.H.	1 1	NRC PDR	1 1
NSIC	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK.
 ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 22 ENCL 22





UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
801 WARRENVILLE ROAD
LISLE, ILLINOIS 60532-4351

NRR
FCC
LPA

FEB 07 1994

Docket No. 50-315
No. 50-316

Indiana Michigan Power Company
ATTN: Mr. E. E. Fitzpatrick
Vice President
Nuclear Operations Division
1 Riverside Plaza
Columbus, OH 43216

Dear Mr. Fitzpatrick:

This refers to the routine safety inspection conducted by J. A. Isom and D. J. Hartland of this office on December 8, 1993, through January 18, 1994, of activities at the Donald C. Cook Nuclear Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-58 and DPR-74, and to the discussion of our findings with A. A. Blind and others of your staff at the conclusion of the inspection.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

During this inspection, certain of your activities appeared to be in violation of NRC requirements. However, as described in the enclosed inspection report, you identified these violations, and to encourage and support licensee initiatives for self-identification and correction of violations, the violations are not being cited because the criteria specified in Section VII.B of the "General Statement of Policy and Procedure for NRC Enforcement Actions," (Enforcement Policy, 10 CFR Part 2, Appendix C (1993)), were satisfied.

We are concerned with the delay in returning two non-safety related 4.16 kV breakers to service after preventive maintenance activities were completed due to ineffective communication between the operations and maintenance personnel. We have reviewed your corrective actions and at this time have no further comments. This area will be monitored in future inspections.

9402160111 940207
PDR ADDCK 05000315
Q PDR

TEL
11



FEB 07 1994


Indiana Michigan Power Company

2

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



Wayne J. Kropp, Chief
Reactor Projects Section 2A

Enclosure:

Inspection Report

No. 50-315/93024(DRP);

No. 50-316/93024(DRP)

cc w/enclosures:

A. A. Blind, Plant Manager

DCD/DCB (RIDS)

OC/LFDCB

Resident Inspector, RIII

James R. Padgett, Michigan

Public Service Commission

EIS Coordinator, USEPA

Region 5 Office

Michigan Department of

Public Health

D. C. Cook, LPM, NRR