CATEGORY 2

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9702070466 DOC.DATE: 97/02/04 NOTARIZED: NO DOCKET #
FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315
50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana M 05000316

AUTH. NAME AUTHOR AFFILIATION

GRANT, G.E. Region 3 (Post 820201)
RECIPIENT AFFILIATION

FITZPATRICK, E. American Electric Power Co., Inc.

SUBJECT: Forwards insp rept 50-315/96-13 & 50-316/96-13 on 961213 & notice of violation.

DISTRIBUTION CODE: 1E01D COPIES RECEIVED:LTR LENCL SIZE: 4+ 40
TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

C

T

E

G

R

Y

D

M

E

N

T

NOTES:

	RECIPIENT ID CODE/NAME PD3-3 PD	COPII LTTR 1		RECIPIENT ID CODE/NAME HICKMAN,J	COP LTTR 1	IES ENCL 1	
INTERNAL:	AEOD/SPD/RAB DEDRO NRR/DI\$P/PIPB NRR/DRPM/PECB NUDOCS-ABSTRACT OGC/HDS2	1 1 1 1 1	1 1 1 1	AEOD/TTC FILE CENTER NRR/DRCH/HHFB NRR/DRPM/PERB OE DIR RGN3 FILE 01	1 1 1 1 1 1 1	1 1 1 1	,
EXTERNAL:	LITCO BRYCE, J H NRC PDR .	1 1	1	NOAC	1	1	

NOTE TO ALL "RIDS" RECIPIENTS: PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083



• ÿ

EA 97-20

Mr. E. E. Fitzpatrick
Senior Vice President
Nuclear Generation Group
American Electric Power Company
500 Circle Drive
Buchanan, MI 49107-1395

SUBJECT: SYSTEM OPERATIONAL PERFORMANCE INSPECTION (SOPI) REPORT

NOS. 50-315/96013(DRS); 50-316/96013(DRS), NOTICE OF DEVIATION.

AND NOTICE OF VIOLATION

Dear Mr. Fitzpatrick:


On December 13, 1996, the NRC completed a system operational performance inspection (SOPI) at your Donald C. Cook facility. The enclosed report presents the results of that inspection.

Based on the inspection results, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice of Violation (Notice). The violations are of concern because timely corrective actions for identified problems, adherence to station procedures, adequate procedures, and appropriate testing acceptance criteria, are all important aspects of safe plant operation. In particular, we are concerned about problems identified regarding our design performance review of the centrifugal charging pumps.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific actions taken and any additional actions you plan to take to prevent recurrence. After reviewing your response to this Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

Also, based on the results of this inspection, certain of your activities, set forth in the enclosure to this letter, appear to be a deviation from commitments which you have made in previous correspondence with the Commission regarding the use of NUREG-0737 assumptions in the design basis accident radiological analysis. A written response is requested.

In addition, the inspectors identified several examples where technical specification interpretations could not be technically justified. Although the consequences of the inadequate interpretations were not significant, we are concerned about the effectiveness of the technical specification interpretation review process and the possibility that



additional technical specification interpretation problems may exist. As a result, and as discussed at the December 13, 1996 exit meeting, you committed to provide the results of your review of your remaining technical specification interpretations. You are requested to provide these results within 30 days of receipt of this letter.

Also, at the end of the inspection, the inspectors were provided with calculations which were subsequently reviewed. As a result of that review, additional questions were developed as discussed in Attachments A and B of this report. You are requested to provide, within 60 days of receipt of this letter, a written response to these questions.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter, its enclosures, and your response will be placed in the NRC Public Document Room (PDR). To the extent possible, your response should not include any personal privacy, proprietary, or safeguards information so that it can be placed in the PDR without redaction.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

/s/ G. E. Grant

Geoffrey E. Grant, Director Division of Reactor Safety

Docket Nos.: 50-315, 50-316 License Nos.: DPR-58, DPR-74

Enclosures:

- 1. Notice of Deviation
- 2. Notice of Violation
- 3. Inspection Report

No. 50-315/96013(DRS); No. 50-316/96013(DRS)

See Attached Distribution

DOCUMENT NAME: G:\DRS\DCC96013.DRS SEE ATTACHED CONCURRENCES

To receive a copy of this document, indicate in the box "C" = Copy w/o attach/encl "E" = Copy w/attach/encl "N" = No copy

OFFICE	RIII:DRS	RIII:DRS	RIII:DRP	RIII:DRS
NAME	Duncan/Butler	Garder/Ring	Miller	Leach/Orant
DATE	01/ /97	01/ /97	01/ /97	02/4/97

OFFICIAL RECORD COPY

Also, at the end of the inspection, the inspectors were provided with calculations which were subsequently reviewed. As a result of that review, additional questions were developed for which additional information is required as discussed in Attachments A and B of this report. You are requested to provide, within 60 days of receipt of this letter, a written response to these requests.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter, its enclosures, and your response will be placed in the NRC Public Document Room (PDR). To the extent possible, your response should not include any personal privacy, proprietary, or safeguards information so that it can be placed in the PDR without redaction.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Geoffrey E. Grant, Director Division of Reactor Safety

Docket Nos.: 50-315, 50-316 License Nos.: DPR-58, DPR-74

Enclosures:

Notice of Violation
 Inspection Report

No. 50-315/96013(DRS); No. 50-316/96013(DRS)

cc w/encls:

A. A. Blind, Site Vice President John Sampson, Plant Manager James R. Padgett, Michigan Public

Service Commission

Michigan Department of Public Health

SEE ATTACHED CONCURRENCES

DOCUMENT NAME: G:\DRS\DCC96013.DRS

To receive a copy of this document, indicate in the box "C" = Copy w/o attach/encl "E" = Copy w/attach/encl "N" = No copy

OFFICE	BIII:DRS	E RIII:DRS E	RIII:DRP	RIII:DRS
NAVE	Duncan/But le	150 Garder/Ring/M	Wilter Burgoss	Leach/Grant
DATE	01/21 /97	-01/ 25/97	01/ 28/97	01/ /97

cc w/encls:

A. A. Blind, Site Vice President

John Sampson, Plant Manager James R. Padgett, Michigan Public

Service Commission

Michigan Department of Public Health

Distribution:

Docket File w/encl

OC/LFDCB w/encl

DRP w/encl

DRS w/encl

RIII PRR w/encl

SRI, D. C. Cook w/encl

LPM, NRR w/encl

A. B. Beach, RIII w/encl

W. L. Axelson, RIII w/encl

Enf. Coordinator, RIII w/encl

CAA1 w/encl

J. Lieberman, OE w/encl

J. Goldberg, OGC w/encl

R. Zimmerman, NRR w/encl

070050