

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9710030018 DOC. DATE: 97/09/29 NOTARIZED: NO DOCKET #
FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315
AUTH. NAME AUTHOR AFFILIATION
GILLESPIE, B. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele
BLIND, A.A. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele
RECIP. NAME RECIPIENT AFFILIATION

SUBJECT: LER 97-016-00: on 970912, determined that RHR sys had operated outside design basis for sys. Cause indeterminate. Revised applicable normal sys operating procedures & will complete evaluation of safety consequences re event. W/970929 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:


	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD3-3 PD	1 1	HICKMAN, J	1 1
INTERNAL:	AEOD/SPD/RAB	2 2	AEOD/SPD/RRAB	1 1
	FILE CENTER	1 1	NRR/DE/ECGB	1 1
	NRR/DE/EELB	1 1	NRR/DE/EMEB	1 1
	NRR/DRCH/HHFB	1 1	NRR/DRCH/HICB	1 1
	NRR/DRCH/HOLB	1 1	NRR/DRCH/HQMB	1 1
	NRR/DRPM/PECB	1 1	NRR/DSSA/SPLB	1 1
	NRR/DSSA/SRXB	1 1	RES/DET/EIB	1 1
	RGN3 FILE 01	1 1		
EXTERNAL:	L ST LOBBY WARD	1 1	LITCO BRYCE, J H	1 1
	NOAC POORE, W.	1 1	NOAC QUEENER, DS	1 1
	NRC PDR	1 1	NUDOCS FULL TXT	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED
TOTAL NUMBER OF COPIES REQUIRED: LTTR 24 ENCL 24

C
A
T
E
G
O
R
Y
1
D
O
C
U
M
E
N
T



Indiana Michigan
Power Company
Cook Nuclear Plant
One Cook Place
Bridgman, MI 49106



September 29, 1997

United States Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Operating Licenses DPR-58
Docket No. 50-315

Document Control Manager:

In accordance with the criteria established by 10 CFR 50.73 entitled Licensee Event Report System, the following report is being submitted:

97-016-00

Sincerely,

A handwritten signature in cursive script that reads 'A. A. Blind'.

A. A. Blind
Site Vice President

/mbd

Attachment

c: A. B. Beach, Region III
E. E. Fitzpatrick
P. A. Barrett
S. J. Brewer
J. R. Padgett
D. Hahn
Records Center, INPO
NRC Resident Inspector

9710030018 970929
PDR ADOCK 05000315
S PDR

IE-01





11
12

LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)
Donald C. Cook Nuclear Plant - Unit 1

DOCKET NUMBER (2)
50-315

Page 1 of 1

TITLE (4)
Interim LER - Operation of RHR Contrary to the FSAR Results in a Degraded Condition While Shutdown

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
09	12	97	97	-- 016 --	00	09	29	97	Cook, Unit 2	50-316
									FACILITY NAME	DOCKET NUMBER

OPERATING MODE (9)	5	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 50. (Check one or more) (11)								
POWER LEVEL (10)	0	20.2201(b)	20.2203(a)(3)(I)	50.73(a)(2)(iii)	73.71(b)					
		20.2203(a)(1)	20.2203(a)(3)(ii)	50.73(a)(2)(iv)	73.71					
		20.2203(a)(2)(I)	20.2203(a)(4)	50.73(a)(2)(v)	OTHER					
		20.2203(a)(2)(ii)	50.36(c)(1)	50.73(a)(2)(vii)	(Specify in Abstract below and in Text, NRC Form 366A)					
		20.2203(a)(2)(iii)	50.36(c)(2)	50.73(a)(2)(viii)(A)						
20.2203(a)(2)(iv)	50.73(a)(2)(I)	50.73(a)(2)(viii)(B)								
20.2203(a)(2)(v)	X 50.73(a)(2)(ii)	50.73(a)(2)(x)								

LICENSEE CONTACT FOR THIS LER (12)

NAME
Mr. Bob Gillespie, Operations Superintendent

TELEPHONE NUMBER (Include Area Code)
616/465-5901, x2535

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)

X	YES	NO	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
				11	17	97

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

On September 12, 1997 with Units 1 and 2 in cold shutdown, it was determined that the Residual Heat Removal (RHR) system had operated outside the design basis for the system. It was determined that this was reportable under 10CFR50.72(b)(2)(i), and an ENS notification was made at 1519 hours on September 12, 1997. This interim LER is being submitted under 10CFR50.73(a)(2)(ii).

Chapter 9 of the FSAR states that only one RHR pump will be operated when the Reactor Coolant System (RCS) is open to atmosphere to prevent damaging both pumps in the unlikely event suction should be lost. Contrary to that statement, the then current operating procedures did not prevent the operation of both RHR pumps when RCS was open to atmosphere. In the past both RHR pumps have been run when the RCS was vented to atmosphere.

Investigation into this condition continues. The Operations department has revised the applicable normal system operating procedures to prevent the operation of both RHR pumps when the RCS is open to atmosphere. Evaluation of the safety consequences of this condition will be completed and an update to this interim LER will be issued by November 17, 1997.

