



Indiana Michigan
Power Company
Cook Nuclear Plant
One Cook Plant
Bridgman, MI 49106
616 465 5901



December 11, 1998

United States Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Operating License DPR-58
Docket No. 50-315

Document Control Manager:

In accordance with the criteria established by 10 CFR 50.73 entitled Licensee Event Report System, the following report is being submitted:

LER 315/98-031-01, "Potential Common Mode Failure of Residual Heat Removal Pumps Due to Use of Inaccurate Values".

The following commitment was identified in this submittal:

- Replace flow instruments and calibrate using new setpoints.

Sincerely,

J. R. Sampson
Site Vice President

/mbd
Attachment

c: J. L. Caldwell (Acting), Region III
R. P. Powers
P. A. Barrett
J. B. Kingseed
R. Whale
D. Hahn
Records Center, INPO
NRC Resident Inspector

9812150143 981211
PDR ADOCK 05000315
S PDR