



October 11, 1978

PRN-LI-78-295

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303


Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 251-78-12
TURKEY POINT UNIT 4
DATE OF OCCURRENCE: SEPTEMBER 27, 1978

CYCLE 5
CORE LOADING PATTERN

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9.2 to provide prompt notification of the subject occurrence.

Very truly yours,


A.D. Schmidt
Vice President
Power Resources

REGULATORY DOCKET FILE COPY

WAK/mla

Attachment

cc: Robert Lowenstein, Esquire
Director, Office of Inspection and Enforcement (40)
✓ Director, Office of Management Information and
Program Control (3)

REGULATORY DOCKET FILE COPY

7810200114

A002
5/11



12