

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

011 | F | L | I | T | P | I | S | 4 | 2 | 0 | 1 | 0 | - | 1 | 0 | 1 | 0 | 1 | 0 | 1 | 0 | 1 | - | 1 | 0 | 1 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 1 | 1 | 4 | 1 | 5 |  
7 3 9 14 15 23 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39

011 | L | 5 | 1 | 0 | 1 | 5 | 1 | 0 | 1 | 0 | 1 | 2 | 5 | 1 | 7 | 1 | 0 | 1 | 9 | 1 | 2 | 1 | 7 | 1 | 7 | 1 | 8 | 3 | 1 | 1 | 1 | 1 | 1 | 7 | 1 | 8 | 9 |  
7 3 9 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

012 | Prior to startup for Unit 4 for Cycle 5 operation, an audit of the Cycle 5 |  
 013 | core configuration revealed that fuel assembly N-04 had been loaded in core |  
 014 | position F-14. The NSSS vendor's base core loading pattern called for fuel |  
 015 | assembly N-07 to be loaded in core position F-14. Due to the similarities |  
 016 | between assemblies N-04 and N-07, the substitution had no adverse affect |  
 017 | on the public health and safety. This is the first occurrence of this |  
 018 | type. |  
7 3 9 30

019 | R | I | C | 11 | D | 12 | Z | 13 | F | I | U | E | L | I | X | I | X | 14 | Z | 15 | Z | 16 |  
7 3 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

17 | 1 | 7 | 1 | 8 | 1 | 0 | 1 | 1 | 2 | 1 | 0 | 1 | 1 | T | 0 |  
21 22 23 24 25 26 27 28 29 30 31 32

X | 18 | Z | 19 | C | 20 | Z | 21 | 0 | 1 | 0 | 3 | 6 | N | 23 | N | 24 | N | 25 | W | 1 | 1 | 2 | 1 | 0 | 26 |  
32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

110 | Substitution occurred as a result of misreading a European style 7 as a 4 |  
 111 | on the base core loading pattern as transmitted from the NSSS vendor. |  
 112 | Analyses, evaluations, and reviews by FPI and the vendor concluded that |  
 113 | the Cycle 5 reload safety evaluation remains valid. Validation of the |  
 114 | core loading pattern received from the NSSS vendor will prevent recurrence. |  
7 3 9 30

115 | H | 23 | 0 | 1 | 0 | 1 | 0 | NA | B | 33 | Audit |  
7 3 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

115 | Z | 33 | Z | 34 | NA | NA |  
7 3 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

117 | 0 | 1 | 0 | 1 | 0 | Z | 33 | NA |  
7 3 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

113 | 0 | 1 | 0 | 1 | 0 | 40 | NA |  
7 3 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

119 | Z | 42 | NA |  
7 3 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

211 | N | 44 | NA |  
7 3 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

NAME OF PREPARER M. A. Schoppman PHONE: (305) 552-3802

7810200117



11  
12