FOR BOX 5	29100, MIAMI, F	L 33152
ER CHERRY		(CET)
FLORIDA PO	WER & LIGHT CO	OMPANY

January 11, 1980 L-80-13 Entral

Mr. James P. O'Reilly, Director, Region II Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:JPO 50-250, 50-251 IE BULLETIN 79-28

The subject Bulletin has been reviewed, and we have determined that no NAMCO Model EA 180 Limit Switches are currently installed in safety related systems at Turkey Point Units 3 and 4.

Thirty-six (36) of these switches are being procured in conjunction with planned modifications. A document source inspection has indicated that the switches are free of the condition described in the Bulletin. The switches will be checked again during the receipt inspection.

Very truly yours,

ţ

ç


Robert E. Uhrig

Vice President Advanced Systems & Technology

REU/MAS/cph

cc: Harold Reis, Esquire





.

4

·

* . . .

.

*

.

. ». .