

*Central File*

USNRC REGION II  
ATLANTA, GEORGIA



80 AUG 25 A 9: 36

August 20, 1980  
L-80-275

Mr. James P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII-JPO  
60-250, 250-251  
IE Bulletin 79-17

In accordance with the subject Bulletin, Florida Power & Light Company has conducted visual and ultrasonic examinations on representative samples of circumferential welds in systems identified to contain stagnant, oxygenated, borated water. Our evaluation of the results of these examinations showed no unresolved indications of stress corrosion cracking in the welds.

Very truly yours,

Robert E. Uhrig  
Vice President  
Advanced Systems & Technology

REU/PLP/md

cc: Harold F. Reis, Esquire

*D*

8009160 639

*Q*

