

USNRC REGION II  
ATLANTA, GEORGIA



30 SEP 2 11:34

August 28, 1980  
L-80-282

Mr. James P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr O'Reilly:

Re: RII: RVL  
50-250/80-26  
50-251/80-26

Florida Power & Light Company has reviewed the subject inspection report and a response is attached.

There is no proprietary information in the report.

Very truly yours,

Robert E. Uhrig  
Vice President  
Advanced Systems & Technology

REU/PLP/md

Attachment

cc: Harold F. Reis, Esquire

8010150576

OFFICIAL COPY

PEOPLE...SERVING PEOPLE



ATTACHMENT

Re: RII: RVL  
50-250/80-26  
50-251/80-26

FINDING:

As required by 10 CFR 20 Paragraph 20.203f, each container of licensed material shall bear a durable, clearly visible label identifying the radioactive contents. It shall also provide sufficient information to permit individuals handling or using the containers, or working in the vicinity thereof to take precautions to avoid or minimize exposures.

Contrary to the above, a cart mounted shielded container storing radioactive filter material was found unattended and unlabeled in the gas analyzer area of the plant hot lab, away from its normal storage location in the plant's cold lab.

RESPONSE:

As corrective action, the radioactive filter material was disposed of in accordance with approved Health Physics procedures and the cart was returned to its prescribed storage location. In order to prevent recurrence, the cart has been labeled, "radioactive material" in order to bring to the attention of individuals working in the area of the cart that proper precautions must be taken to avoid or minimize exposures.

Full compliance was achieved on August 15, 1980.

