

LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0][1] [I][L][D][R][S][3] [2] [0][0]-[0][0][0][0][0]-[0][0] [3] [4][1][1][1][1] [4] [5]
7 8 9 14 15 25 26 30 57 CAT 58
LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CON'T [0][1] REPORT SOURCE [L] [6] [0][5][0][0][0][2][4][9] [7] [0][3][0][5][8][0] [8] [0][3][2][8][8][0] [9]
7 8 60 61 68 69 74 75 80
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[0][2] During Unit 3 shutdown, while conducting steam line area temperature switch calibration
[0][3] surveillance, temp. switch TS 3-261-17B tripped at 203.1 deg. F. Tech. Spec. Table
[0][4] 3.2.1 requirement is < /= 200 degrees F. This is of minimum safety significance be-
[0][5] cause even with 1 switch not functioning correctly, all four trip channels were oper-
[0][6] able. This is the first occurrence for this type of switch.

[0][9] SYSTEM CODE [C][I] (11) CAUSE CODE [E] (12) CAUSE SUBCODE [A] (13) COMPONENT CODE [I][N][S][T][R][U] (14) COMP. SUBCODE [S] (15) VALVE SUBCODE [Z] (16)
7 8 9 10 11 12 13 18 19 20

(17) LER/RO REPORT NUMBER [8][0] EVENT YEAR [ ] SHUTDOWN METHOD [Z] (21) HOURS [0][0][0][0] (22) ATTACHMENT SUBMITTED [N] (23) NPRO-4 FORM SUB. [Y] (24) PRIME COMP. SUPPLIER [N] (25) COMPONENT MANUFACTURER [U][0][7][5] (26)
21 22 23 24 26 27 28 29 30 31 32
ACTION TAKEN [E] (18) FUTURE ACTION [X] (19) EFFECT ON PLANT [Z] (20)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

[1][0] Event was caused by dirt deposits on the switch actuation plunger. Switch was adjusted
[1][1] to trip at 181.6 deg. F. increasing and verified for repeated operability. Switch
[1][2] mechanism was also cleaned and exercised. All steam line area temperature switches
[1][3] shall continue to be tested during each refueling outage.

[1][5] FACILITY STATUS [H] (28) % POWER [0][0][0] (29) OTHER STATUS [N/A] (30) METHOD OF DISCOVERY [B] (31) DISCOVERY DESCRIPTION [Surveillance] (32)
7 8 9 10 12 13 44 45 46 80

[1][6] ACTIVITY CONTENT [Z] (33) RELEASED OF RELEASE [Z] (34) AMOUNT OF ACTIVITY [N/A] (35) LOCATION OF RELEASE [N/A] (36)
7 8 9 10 11 44 45 80

[1][7] PERSONNEL EXPOSURES NUMBER [0][0][0] (37) TYPE [Z] (38) DESCRIPTION [N/A] (39)
7 8 9 11 12 13 80

[1][8] PERSONNEL INJURIES NUMBER [0][0][0] (40) DESCRIPTION [N/A] (41)
7 8 9 11 12 80

[1][9] LOSS OF OR DAMAGE TO FACILITY TYPE [Z] (42) DESCRIPTION [N/A] (43)
7 8 9 11 12 80

[2][0] PUBLICITY ISSUED [N] (44) DESCRIPTION [N/A] (45)
7 8 9 10 80
Randy Speroff
8004080561
NRC USE ONLY
X-526