

APPENDIX B

NOTICE OF DEVIATION:

Florida Power and Light Company  
Turkey Point 3 & 4

Docket Nos. 50-250 & 50-251  
License Nos. DPR-31 & DPR-41

Based on the results of the NRC inspection conducted on April 6-10 and 13-17, 1981, certain of your activities appear to deviate from your commitments to the Commission as indicated below.

In response to Item A.3 in the Notice of Violation transmitted by the Region II letter dated June 20, 1979, FP&L correspondence dated July 12, 1979, listed the following long term corrective action involving rigging and hoisting equipment:

- (1) The submittal of an exception to the FPL Topical Quality Assurance Report by July 20, 1979 to describe this program.
- (2) Inclusion of this program into Corporate Quality Procedures and Turkey Point Administrative Procedures within 30 days after approval of the Topical Quality Assurance Report revision.
- (3) Full compliance will be achieved upon revision of these procedures.

Revision 3 to the FPL Topical QA Report was submitted as required by item (1). FPL stated during the inspection that full implementation had been achieved on September 1980 as intended by items (2) and (3).

Contrary to the above, inclusion of this program relative to the exception involving rigging and hoisting equipment into Corporate Quality Procedures and Turkey Point Administrative Procedures had not been accomplished as of the date of this inspection.

18106120369

