

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

SESSION NBR:8806020032 DOC.DATE: 88/05/23 NOTARIZED: NO DOCKET #
FACIL:50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
AUTH.NAME AUTHOR AFFILIATION
CLINE,W.E. Region 2, Ofc of the Director
RECIP.NAME RECIPIENT AFFILIATION
WOODY,C.O. Florida Power & Light Co.

SUBJECT: Forwards Insp Rept 50-250/88-09 & 50-251/88-09 on 880418-22.
No violations or deviations noted.

DISTRIBUTION CODE: IE04D COPIES RECEIVED:LTR (ENCL) SIZE: 2+1
TITLE: Safeguards Inspection Rpt/NOV Response (50 DKT) -Publicly Available

NOTES:

Table with 4 columns: RECIPIENT ID CODE/NAME, COPIES LTR ENCL, RECIPIENT ID CODE/NAME, COPIES LTR ENCL. Rows include PD2-2 LA EDISON,G; INTERNAL: AEOD/DOA, NRR/DRIS/SIB 9A, NUDOCS-ABSTRACT, RGN2 FILE 01; EXTERNAL: LPDR, NSIC; and NRR/DRIS/SGB 9D, NRR/PMAS/ILRB12, REG FILE 02, NRC PDR.

R
I
D
S
/
A
D
D
S
R
I
D
S
/
A
D
D
S

TOTAL NUMBER OF COPIES REQUIRED: LTR 13 ENCL 10



SAFEGUARDS INFORMATION
MAY 23 1988

Docket Nos. 50-250, 50-251
License Nos. DPR-31, DPR-41

Florida Power and Light Company
ATTN: Mr. C. O. Woody
Group Vice President
Nuclear Energy Department
P. O. Box 14000
Juno Beach, FL 33408-0420

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NOS. 50-250/88-09 AND 50-251/88-09

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by Ms. O. Masnyk on April 18-22, 1988. The inspection included a review of activities authorized for your Turkey Point facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified.

In accordance with 10 CFR 2.790(d) and 10 CFR 73.21, safeguards activities and security measures are exempt from public disclosure. Therefore, the enclosure to this letter with the exception of the report cover page, which presents a nonexempt summary, will not be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely,

William E. Cline, Chief
Nuclear Materials Safety and
Safeguards Branch
Division of Radiation Safety
and Safeguards

Enclosure: (See page 2)

SAFEGUARDS INFORMATION

8806020032 880523
PDR ADUCK 05000250
Q DCD

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION
ON SEPARATION THIS
MATERIAL IS DECONTROLLED.

JE-04



SAFEGUARDS INFORMATION

Florida Power and Light Company

2

MAY 23 1988

Enclosure:
NRC Inspection Report

cc w/encl:

J. S. Odom, Vice President
Turkey Point Nuclear Plant
C. J. Baker, Plant Manager
Turkey Point Nuclear Plant
L. W. Bladow, Plant QA Superintendent
J. Arias, Jr., Regulatory and Compliance
Supervisor

bcc w/encl:

G. E. Edison, Project Manager, Project
Directorate II-2, Division of Reactor
Projects, NRR
NRC Resident Inspector
DRS Technical Assistant
Document Control Desk
State of Florida

R11

Smis
OMasnyk:ser
05/17/88

R11

DMcGuire
DMcGuire
05/20/88

R11

RCrLenjak
RCrLenjak
05/17/88

R11

LRaves
LRaves
05/17/88

SAFEGUARDS INFORMATION

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION
UPON SEPARATION THIS
PAGE IS DECONTROLLED.

1

