

NUCLEAR LICENSING
OFFICIAL FILE COPY



←

AUGUST 26 1988

L-88-365

CLOSES CTBAC 88-172C

OPENS CTBAC 88-2188

SEP 12 P 3: 51

U.S. NRC RGN.-II
Atlanta, Ga.

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Units 3 and 4
Docket Nos. 80-250 and 50-251
Reply to Notice of Violation
Inspection Report 88-16

Florida Power & Light Company has reviewed the subject inspection report and a response is attached.

Very truly yours,

W. F. Conway
W. F. Conway
Senior Vice President - Nuclear

WFC/SDF/gp

Attachment

cc: Dr. J. Nelson Grace, Regional Administrator,
Region II, USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

SDF.IR

CLARKE DEAN DUNN HARRIS HAYES JOHNSON KANE KIRBY LEVINE LITTLE MALONE MANNING MARTIN MURPHY NELSON O'NEILL PETERSON ROBERTS SCHNEIDER SIMON STEVENSON THOMPSON TOLSON WATSON WOODS	YOUNG	WELLS WILSON WYATT ZIMMERMAN	CHASE CONNELLEY FOLEY GARDNER GLAVIN HARBO HENNINGSEN JONES KAPLAN LADD LONG MURPHY NICHOLS ROSEN SULLIVAN TERRY TRACY WATSON WOODS
--	-------	---------------------------------------	---

8809020263



ATTACHMENT

RE: TURKEY POINT UNITS 3 AND 4
DOCKET NO. 50-250, 50-251
IS INSPECTION REPORT 250-88-16 & 251-88-16

FINDING:

10 CFR 50.54(p)(2) requires licensees to submit "a report containing a description of each change within two months after the change is made" when making a change to the security plan which would not decrease the effectiveness of the plan.

Contrary to the above, in a letter dated April 11, 1988, Revision 13 to the Physical Security Plan was transmitted to the NRC. This revision contained a discussion of a change to the contractor entrance building which was implemented December 28, 1987. This fails to meet the two months reporting requirements.

RESPONSE:

- 1) FPL concurs with the finding.
- 2) The cause of the violation is personnel error and inadequate procedures. The Site Security Group failed to officially notify the Corporate Security Group of the need to revise the Security Plan. Additionally, at the time of the event, there were no formal guidelines for review, approval and submittal to the NRC of Security Plan changes.
- 3) A draft of "Letter of Instruction (LOI) for Security Plan Changes" has been prepared for review and comment. This Letter of Instruction provides requirements for review, approval and submittal to the NRC of Security Plan changes. Corporate and site security are currently working to this draft LOI.
- 4) The review process will be re-evaluated to ensure it properly delineates the requirements for review, approval and submittal of Security Plan changes to the NRC. A corporate procedure will be issued that defines and controls this process.
- 5) Compliance with the draft LOI discussed in item 3 above was achieved by August 26, 1988.

Full compliance for item 4 above will be achieved by October 1, 1988.

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM
 REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8809020263 DOC.DATE: 88/08/26 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH.NAME AUTHOR AFFILIATION
 CONWAY, W.F. Florida Power & Light Co.
 RECIPIENT NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Responds to Insp Repts 50-250/88-16 & 50-251/88-16.


DISTRIBUTION CODE: IE01D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
	PD2-2 PD	1 1	EDISON, G	2 2
INTERNAL:	AEOD	1 1	DEDRO	1 1
	NRR MORISSEAU, D	1 1	NRR/DLPQ/PEB 11	1 1
	NRR/DLPQ/QAB 10	1 1	NRR/DOEA DIR 11	1 1
	NRR/DREP/EPB 10	1 1	NRR/DREP/RPB 10	2 2
	NRR/DRIS DIR 9A	1 1	NRR/PMAS/ILRB12	1 1
	NUDOCS-ABSTRACT	1 1	OF LIEBERMAN, J	1 1
	OGC/HDS2	1 1	<u>REG FILE</u> 02	1 1
	RES/DSIR DEPY	1 1	RGN2 FILE 01	1 1
INTERNAL:	LPDR	1 1	NRC PDR	1 1
	NSIC	1 1		

F
I
I
S
/
A
E
I
S

R
I
D
S
/
A
D
D
S



AUGUST 26 1988

L-88-365

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Reply to Notice of Violation
Inspection Report 88-16

Florida Power & Light Company has reviewed the subject inspection report and a response is attached.

Very truly yours,

A handwritten signature in cursive script that reads 'W. F. Conway'.

W. F. Conway
Senior Vice President - Nuclear

WFC/SDF/gp

Attachment

cc: Dr. J. Nelson Grace, Regional Administrator,
Region II, USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

8809020263 880826
PDR ADDCK 05000250
Q PNU

SDF.IR

IE01
11



ATTACHMENT

RE: TURKEY POINT UNITS 3 AND 4
DOCKET NO. 50-250, 50-251
IE INSPECTION REPORT 250-88-16 & 251-88-16

FINDING:

10 CFR 50.54(p)(2) requires licensees to submit "a report containing a description of each change within two months after the change is made" when making a change to the security plan which would not decrease the effectiveness of the plan.

Contrary to the above, in a letter dated April 11, 1988, Revision 13 to the Physical Security Plan was transmitted to the NRC. This revision contained a discussion of a change to the contractor entrance building which was implemented December 28, 1987. This fails to meet the two months reporting requirements.

RESPONSE:

- 1) FPL concurs with the finding.
- 2) The cause of the violation is personnel error and inadequate procedures. The Site Security Group failed to officially notify the Corporate Security Group of the need to revise the Security Plan. Additionally, at the time of the event, there were no formal guidelines for review, approval and submittal to the NRC of Security Plan changes.
- 3) A draft of "Letter of Instruction (LOI) for Security Plan Changes" has been prepared for review and comment. This Letter of Instruction provides requirements for review, approval and submittal to the NRC of Security Plan changes. Corporate and site security are currently working to this draft LOI.
- 4) The review process will be re-evaluated to ensure it properly delineates the requirements for review, approval and submittal of Security Plan changes to the NRC. A corporate procedure will be issued that defines and controls this process.
- 5) Compliance with the draft LOI discussed in item 3 above was achieved by August 26, 1988.

Full compliance for item 4 above will be achieved by October 1, 1988.



ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM
 REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8809020263 DOC.DATE: 88/08/26 NOTARIZED: NO DOCKET #
 FACIL:50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH.NAME AUTHOR AFFILIATION
 CONWAY,W.F. Florida Power & Light Co.
 RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Responds to Insp Repts 50-250/88-16 & 50-251/88-16.

DISTRIBUTION CODE: IE01D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 2
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTR	ENCL		ID CODE/NAME		LTR	ENCL
	PD2-2 PD		1	1		EDISON,G		2	2
INTERNAL:	AEOD		1	1		DEDRO		1	1
	NRR MORISSEAU,D		1	1		NRR/DLPQ/PEB 11		1	1
	NRR/DLPQ/QAB 10		1	1		NRR/DOEA DIR 11		1	1
	NRR/DREP/EPB 10		1	1		NRR/DREP/RPB 10		2	2
	NRR/DRIS DIR 9A		1	1		NRR/PMAS/ILRB12		1	1
	NUDOCS-ABSTRACT		1	1		OE LIEBERMAN,J		1	1
	OGC/HDS2		1	1		REG FILE 02		1	1
	RES/DSIR DEPY		1	1		<u>RG2 FILE 01</u>		1	1
INTERNAL:	LPDR		1	1		NRC PDR		1	1
	NSIC		1	1					

R
I
D
S
/
A
D
D
S

R
I
D
S
/
A
D
D
S

12





AUGUST 26 1988

L-88-365

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Reply to Notice of Violation
Inspection Report 88-16

Florida Power & Light Company has reviewed the subject inspection report and a response is attached.


Very truly yours,

W. F. Conway
W. F. Conway
Senior Vice President - Nuclear

WFC/SDF/gp


Attachment

cc: Dr. J. Nelson Grace, Regional Administrator,
Region II, USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant



SDF.IR

IEO1
11



ATTACHMENT

RE: TURKEY POINT UNITS 3 AND 4
DOCKET NO. 50-250, 50-251
IE INSPECTION REPORT 250-88-16 & 251-88-16

FINDING:

10 CFR 50.54(p)(2) requires licensees to submit "a report containing a description of each change within two months after the change is made" when making a change to the security plan which would not decrease the effectiveness of the plan.

Contrary to the above, in a letter dated April 11, 1988, Revision 13 to the Physical Security Plan was transmitted to the NRC. This revision contained a discussion of a change to the contractor entrance building which was implemented December 28, 1987. This fails to meet the two months reporting requirements.

RESPONSE:

- 1) FPL concurs with the finding.
- 2) The cause of the violation is personnel error and inadequate procedures. The Site Security Group failed to officially notify the Corporate Security Group of the need to revise the Security Plan. Additionally, at the time of the event, there were no formal guidelines for review, approval and submittal to the NRC of Security Plan changes.
- 3) A draft of "Letter of Instruction (LOI) for Security Plan Changes" has been prepared for review and comment. This Letter of Instruction provides requirements for review, approval and submittal to the NRC of Security Plan changes. Corporate and site security are currently working to this draft LOI.
- 4) The review process will be re-evaluated to ensure it properly delineates the requirements for review, approval and submittal of Security Plan changes to the NRC. A corporate procedure will be issued that defines and controls this process.
- 5) Compliance with the draft LOI discussed in item 3 above was achieved by August 26, 1988.

Full compliance for item 4 above will be achieved by October 1, 1988.

12

