ACCELERATE OLLAPISTRIBUTION DIDEMONSTRATION (RIDSYSTEM

ACCESSION NBR:8809070549 DOC.DATE: 88/09/01 NOTARIZED: NO DOCKET # FACIL:50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251

AUTH.NAME AUTHOR AFFILIATION

TILLMAN, A. Region 2, Ofc of the Director MCGUIRE, D.R. Region 2, Ofc of the Director

RECIPIENT AFFILIATION

SUBJECT: Partially withheld Insp Repts 50-250/88-20 & 50-251/88-20 on

880801-05. One violation noted. Major areas inspected: testing

DISTRIBUTION CODE: IE04D COPIES RECEIVED:LTR / ENCL O SIZE: / TITLE: Safeguards Inspection Rpt/NOV Response (50 DKT)-Publicly Available

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-2 LA EDISON,G	1 9	PD2-2 PD	1
INTERNAL:	AEOD/DOA NRR/DRIS/SIB 9A NUDOCS-ABSTRACT RGN2 FILE 01	1 1 1 1 1 1	NRR/DRIS/SGB 9D NRR/PMAS/ILRB12 REG FILE 02	1 1
	LPDR NSIC	1 1	NRC PDR	1 þ

SAFEGUARDS INFORMATION



NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA STREET, N.W.
ATLANTA, GEORGIA 30323

SEP 1 1988

Report Nos.: 50-250/88-20 and 50-251/88-20

Licensee: Florida Power and Light Company

9250 West Flagler Street

Miami, FL 33102

Docket Nos.: 50-250 and 50-251

License Nos.: DPR-31 and DPR-41

Facility Name: Turkey Point 3 and 4

Inspection Conducted: August 1-5, 1988

Inspector: A Tillman, Rhysical Security Inspector

8/3/88 Date Signed

8/21/88

Approved by: 100 THO

). R. McGuire, Chief

Physical Security Section

Nuclear Materials Safety and Safeguards Branch Division of Radiation Safety and Safeguards

SUMMARY

Scope:

This routine, unannounced inspection was conducted in the areas of Testing and Maintenance; Physical Barriers - Protected Area; Physical Barriers - Vital Areas; Lighting; Compensatory Measures, Assessment Aids; Access Controls - Packages; Detection Aids - Vital Areas; Personnel Training and Qualification - General Requirements; and Physical Protection of Safeguards Information.

Results:

One violation of regulatory requirements was identified - Failure to

maintain adequate compensatory measures.

8809070549 880901 PDR ADDCK 05000250 Q PNU

Document transmitted herewith

colors sensitive unclassified

colors to When separated from

the colors of the separated from

SAFEGUARDS INFORMATION