REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACIL: 50 50 AUTH.NA	D.M. Region 2	Plant, U Plant, U AFFILIATI , Ofc of	Unit 3, Florid Unit 4, Florid TON the Director	da Power and	l Light C	DOCKET # 05000250 05000251
CONWAY,				*		R
SUBJECT: Forwards Insp Repts 50-250/89-08 & 50-251/89-08 on 1 890313-17. Violations noted. NOV not being issued.						
DISTRIBUTION CODE: IE35D COPIES RECEIVED:LTR _ ENCL _ SIZE: 5+9 D TITLE: Emergency Preparedness-Appraisal/Confirmatory Action Ltr/Exercise Rep S						
NOTES:						. /
	RECIPIENT ID CODE/NAME PD2-2 PD	COPIES LTTR EN 1	ICL ID COI	PIENT DE/NAME G	COPIES LTTR ENC 1 1	L A
·	NRR/DREP/EPB 10 NUDOCS ABSTRACT REG FILE 02 RGN2/DRSS/EPRPB	1 1 1 1 1 1	OC/LFMB	S/ILRB12 FILE 01	1 1 1 0 1 1	D S
EXTERNAL:	LPDR NSIC	1 1	NRC PDR		1 1	

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

R

I

D

S

TOTAL NUMBER OF COPIES REQUIRED: LTTR 12 ENCL 11

Docket Nos. 50-250, 50-251 License Nos. DPR-31, DPR-41

Florida Power and Light Company ATTN: Mr. W. F. Conway Senior Vice President - Nuclear P. O. Box 14000 Juno Beach, FL 33408-0420

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NOS. 50-250/89-08 AND 50-251/89-08

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by A. L. Cunningham on March 13-17, 1989. The inspection included a review of activities authorized for your Turkey Point facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

The inspection findings indicate that certain activities appeared to violate NRC requirements. However, a Notice of Violation is not being issued based on your prompt initiation and completion of corrective actions; therefore, no response is required.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please contact us.


Sincerely,

Etiginal Signoù By E. M. Collins

Douglas M. Collins, Chief Emergency Preparedness and Radiological Protection Branch Division of Radiation Safety and Safeguards

Enclosure: (See page 2)

8904250157 890417 PDR ADOCK 05000250 D PDC



Enclosure: NRC Inspection Report

cc w/encl:

J. S. Odom, Vice President Turkey Point Nuclear Plant

J. E. Cross, Plant Manager Turkey Point Nuclear Plant

L. W. Bladow, Plant QA Superintendent

J. Arias, Jr., Regulatory and Compliance Supervisor

State of Florida

bcc w/encl:

G. E. Edison, Project Manager, Project Directorate II-2, Division of Reactor Projects, NRR

NRC Resident Inspector

W. D. Travers, NRR

J. C. Heard, FEMA RIV

RII Acumningham 4//89 WRankin 4/17/89

RChlenjak 4/17/89

