

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8906070222 DOC. DATE: 89/05/31 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH. NAME AUTHORITY AFFILIATION
 WOODY, C.O. Florida Power & Light Co.
 RECIPIENT NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Special rept re breached fire barriers & other fire protection sys impairments.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTR	ENCL		ID CODE/NAME		LTR	ENCL
	PD2-2 LA		1	1		PD2-2 PD		1	1
	EDISON, G		1	1					
INTERNAL:	ACRS MICHELSON		1	1	ACRS MOELLER		2	2	
	ACRS WYLIE		1	1	AEOD/DOA		1	1	
	AEOD/DSP/TPAB		1	1	AEOD/ROAB/DSP		2	2	
	DEDRO		1	1	IRM/DCTS/DAB		1	1	
	NRR/DEST/ADE 8H		1	1	NRR/DEST/ADS 7E		1	0	
	NRR/DEST/CEB 8H		1	1	NRR/DEST/ESB 8D		1	1	
	NRR/DEST/ICSB 7		1	1	NRR/DEST/MEB 9H		1	1	
	NRR/DEST/MTB 9H		1	1	NRR/DEST/PSB 8D		1	1	
	NRR/DEST/RSB 8E		1	1	NRR/DEST/SGB 8D		1	1	
	NRR/DLPQ/HFB 10		1	1	NRR/DLPQ/PEB 10		1	1	
	NRR/DOEA/EAB 11		1	1	NRR/DRER/RPB 10		2	2	
	NUDOCS-ABSTRACT		1	1	<u>REG FILE</u> 02		1	1	
	RES/DSIR/EIB		1	1	RES/DSR/PRAB		1	1	
	RGN2 FILE 01		1	1					
EXTERNAL:	EG&G WILLIAMS, S		4	4	FORD BLDG HOY, A		1	1	
	L ST LOBBY WARD		1	1	LPDR		1	1	
	NRC PDR		1	1	NSIC MAYS, G		1	1	
	NSIC MURPHY, G.A		1	1					

1/A-2
ell

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 43 ENCL 42



MAY 31 1989

L-89-195

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Special Report - Breached Fire Barriers and
Other Fire Protection System Impairments

In accordance with Technical Specification 6.9.3.c, the attached Special Report is provided for your information.

Should there be any questions on this information, please contact us.

Very truly yours,

A handwritten signature in dark ink, appearing to read "C. O. Woody", is written over the typed name.

C. O. Woody
Acting Senior Vice President - Nuclear

COW/JRH/cm

Attachment

cc: Stewart D. Ebnetter, Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

8906070222 890531
PDR ADCK 05000250
S PNU

IE22
/1

Attachment:

SPECIAL REPORT

FIRE PROTECTION SYSTEM IMPAIRMENTS REQUIRING NRC NOTIFICATION

PURPOSE:

Technical Specification (TS) 3.14.5.b requires the submission of a report to the NRC if a non-functional fire barrier penetration is not returned to functional status within 7 days. TS 3.14 also states that certain other conditions require NRC notification. In accordance with the above requirements, this special report is being submitted in order to notify the NRC.

EVENT:

Fire Protection Impairment (FPI) 2458 was opened for penetration 025W-E016.

CAUSE AND CORRECTIVE ACTIONS:

FPI 2458, opened April 20, 1989 to repair a penetration seal, is still being worked. The plant continues to implement the compensatory measures as applicable.

STATUS UPDATE:

FPI 1778, reported open in FPL letter L-88-331, dated August 2, 1988, was closed on April 14, 1989. FPI 2059, reported open in FPL letter L-88-501, dated November 18, 1988, was closed on April 18, 1989. FPI 2137, reported open in FPL letter L-88-535, dated December 16, 1988, was closed on April 19, 1989. FPIs 2301 and 2302, reported open in FPL letter L-89-114, dated March 23, 1989, were closed on May 3, 1989. FPI 2365, reported open in FPL letter L-89-154, dated April 21, 1989, was closed on April 18, 1989.