

March 7, 1991

Florida Power and Light Company
ATTN: Mr. J. H. Goldberg, President
Nuclear Division
P. O. Box 14000
Juno Beach, FL 33408-0420

Gentlemen:

SUBJECT: TURKEY POINT EXAMINATION REPORT - 50-250/OL-91-01

On January 21-31, 1991, the NRC administered written and operating examinations to employees of your company who had applied for licenses to operate the Turkey Point Nuclear Plant. At the conclusion of these examinations, the examination questions and preliminary findings were discussed with those members of your staff identified in this examination report.

The following weaknesses were identified during administration of these examinations and were discussed with facility representatives during the exit meeting. The weaknesses are detailed in Section 5 of Enclosure 1.

Incorrect classification caused by unclear wording of the plant emergency classification table.

Lack of procedural guidance for responding to a 30% dropped control rod turbine runback caused by a rod position indication failure.

Lack of procedural guidance for response to, and diagnosis of, instrumentation induced Anticipated Transient without scram conditions.

A written response to this office, including proposed corrective action, to each of these identified weaknesses is requested.

The responses requested by this letter, and its enclosures, are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, Pub. L. No. 96-511.

9103270068 910307
PDR ADOCK 05000250
V PDR

|||
IE 42



March 7, 1991

In accordance with 10 CFR 2.790(a), a copy of this letter and its enclosures will be placed in NRC's Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely,

(ORIGINAL SIGNED BY T. A. PEEBLES FOR)

Albert F. Gibson, Director
Division of Reactor Safety

Enclosures:

- 1. Examination Report No. 50-250/OL-91-01
- 2. SRO Examination & Answer Key
(Document Control Room Only)
- 3. Simulation Facility Fidelity Report

cc w/encls 1 and 3:

- P. N. McCullough, Manager, Nuclear Training
- T. F. Plunkett, Site Vice President
- K. E. Beatty, Training Superintendent

cc w/encl 1:

State of Florida

bcc w/encl 1:

- G. Edison, Project Manager, NRR
- R. Crlenjak, Section Chief, DRP
Senior Resident Inspector
- J. Moorman III, Principal Examiner, DRS
- C. Rapp, Chief Examiner, DRS

bcc w/encls 1, 2, and 3:

Document Control Desk

bcc w/encls 1 and 3:

Operator Licensing Branch, DLPQ:NRR

*FOR PREVIOUS CONCURRENCE - SEE ATTACHED COPY

RII:DRS

RII:DRS

RII:DRP

RII:DRS

RII:DRS


*CRapp
02/ /91

*CCasto
02/ /91

*RCrlenjak
02/ /91

*TPeebles
02/ /91

788
AFGibson
03/7 /91



Florida Power and Light Co. 3

bcc w/encl 1:

G. Edison, Project Manager, NRR
R. Crlenjak, Section Chief, DRP
Senior Resident Inspector
J. Moorman III, Principal Examiner, DRS
C. Rapp, Chief Examiner, DRS

bcc w/encls 1, 2, and 3:
Document Control Desk

bcc w/encls 1 and 3:
Operator Licensing Branch, DLPQ:NRR

*FOR PREVIOUS CONCURRENCE - SEE ATTACHED COPY

RII:DRS

*CRapp
02/ /91

RII:DRS

*CCasto
02/ /91

RII:DRP

WC
RCrlenjak
02/27/91

RII:DRS

71
AFGibson
02/ /91

1/28
2/27/91



Florida Power and Light Co. 3

bcc w/encl 1:

G. Edison, Project Manager, NRR

R. Crlenjak, Section Chief, DRP

Senior Resident Inspector

J. Moorman III, Principal Examiner, DRS

C. Rapp, Chief Examiner, DRS

bcc w/encls 1, 2, and 3:

Document Control Desk

bcc w/encls 1 and 3:

Operator Licensing Branch, DLPQ:NRR

RII:DRS

CR
CRapp

02/25/91

RII:DRS

CC
CCasto

02/25/91

RII:DRP

RCrlenjak

02/ /91

RII:DRS

TAPeebles

02/ /91

