DUC.DATE: 83/04/08 NOTARIZED: NO DOCKET # FACIL:50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251

AUTHUR AFFILIATION AUTH.NAME

UHRIG, R.E. RECIP.NAME EISENHUT, D.G.

ACCESSION NBR:8304140242

Florida Power & Light Co. RECIPIENT AFFILIATION Division of Licensing

SUBJECT: Commits to test all affected equipment & perform surveillance required by Tech Specs, per 821110 ltr, during steam generator repair outage prior to fuel reload.

DISTRIBUTION CODE: A0018 COPIES RECEIVED:LTR _ ENCL L_ TITLE: OR Submittal: General Distribution

NOTES:

	RECIPIENT ID CODE/NAM	COPIES LTTR ENCL		RECIPIENT ID CODE/NAME		COPIES LTTR ENCL		
	NRR ORB1 BC	01	7	7	•	1		
INTERNAL:	ELD/HDS4		1	0	NRR/DE/MTEB		1	1
4	NRR/DL DIR		1	1	NRR/DL/ORAB		1	0 '
	NRR/DSI/METB		1	1	NRR/DSI/RAB		1	1
	REG FALE	04	1	1	RGN2		1	1
EXTERNAL:	ACRS	09	6	6	LPDR	03	1	1
	NRC PDR	02	1	1	NSIC	05	1	1
	NTIS		1	1	,			

Section 2 ACCOUNT OF THE CONTRACT SANCES SANCES SANCES SANCES SANCES SANCES AND ACCOUNTS A CONTRACT OF THE CONTRACT CONTR H AND I FERRAL A FARE TO THE REST OF EACH A REPORT REPORT OF THE RESIDENCE OF THE PROPERTY OF THE PROPER TVICTO AT LICENTAL NA

> erofrong a more real materials of few particular properties for form Enrapolation of the solution of the contract o steam depointed religion and on a rest to fuel relocat.

alaber of the contract of the Indies sate authorite fortored kasteakahan

20 18 Jul

	CODJ MELL		41 141 1 1 ⁴³ \ 44 41 4		11 10 to		FULLILLY X	
				1	Y	X (6 .)	is to a state	
1	1	, 1°	\$ 4\ _e } \$\ 124; \	. *	ì.		Be late 1x	2 Inches de al 1
4 11	ì	P\$145	Fleir Yell William	*	1		1111 1 1 1 1 1	
i	1	/ k . "	and hour	ſ	1	м 1	A VINTER AVAILABLE	
ı	f		1. 3.5 M to 1.	ú	<u>.</u>		BALL Color	
À	ı	k _a	### 1	ي. الإ	ъ 3	√ f	e ngg 🎉 🏄 t	: 16 1 (1(X)
x	í	_R 1	of I est"	Į	l.	, C)	28 H N 4 48 11 11 2	
				j	 X		S. L. T. Cal	



Office of Nuclear Reactor Regulation

Attention: Mr. Darrell G. Eisenhut, Director

Division of Licensing

U.S. Nuclear Regulatory Commission

Washington, D. C. 20555

Dear Mr. Eisenhut:

Re:

Turkey Point Unit 4 Docket No. 50-251

Technical Specification Exemption during Steam Generator Repair Outage

Our letter L-82-497, dated November 10, 1982, identified various surveillance requirements required by our Technical Specifications which we did not intend to implement during the Steam Generator Repair Outage. This was due to the fact that fuel was removed from the reactor vessel during the length of the outage. We inadvertently left out a commitment to test all the affected equipment prior to reloading fuel into the reactor.

The purpose of this letter is to state our commitment to test the affected equipment and to perform the surveillances required by Technical Specifications referenced in L-82-497 prior to reloading fuel into the reactor and to resume normal surveillance frequencies at that time.

Very truly yours,

Robert E. Uhrig

Vice President

Advanced Systems & Technology

REU/JEM/js

cc: Mr. James P. O'Reilly, Region II

Mr. Harold F. Reis, Esquire

A001

• • • , u.