

March 11, 1985

Docket Nos. 50-250
and 50-251

<u>Distribution</u>	<u>Docket file</u>
NRC PDR	L-PDR
ORB#1 RDG	HThompson
OELD	EJordan
BGrimes	JPartlow
DMcDonald	CParrish
ACRS (10)	ORB#1 Gray file
TAlexion	RAuluck
DShasher	JStevens
DBeckham	

Mr. J. W. Williams, Jr., Vice President
Nuclear Energy Department
Florida Power and Light Company
Post Office Box 14000
Juno Beach, Florida 33408

Dear Mr. Williams:

Reference: TAC Numbers 53726, 53727, 54036 and 54037

SUBJECT: REQUEST FOR ADDITIONAL INFORMATION FOLLOWING PRELIMINARY
STAFF REVIEW OF TURKEY POINT UNITS 3 AND 4 RESPONSES TO
GENERIC LETTER 83-28

The staff has completed a preliminary review to assess the completeness and adequacy of licensee responses to Generic Letter 83-28 Items 2.1, 2.2, 3.1.3, 3.2.3, 4.4 and 4.5. For the Turkey Point Plant, your responses were found to be incomplete for Items 2.2.2 and 4.5.3. Brief descriptions of the deficiencies are given as guidelines for corrective action in the enclosed request for additional information. Efforts by Owners Groups, INPO and NSSS Vendors have been or are being made to produce generic responses that may be useful in meeting the requirements of the above items. You may wish to contact your Owner's Group or INPO regarding the applicability of such generic responses to your plant.

In order to preserve our present review schedule, the staff needs to have the supplementary information within 60 days for Item 2.2.2, and within 90 days for Item 4.5.3. We request your cooperation in meeting this schedule.

This request for additional information was approved by the Office of Management and Budget under clearance number 3150-0011 which expires April 30, 1985. Comments on burden and duplication may be directed to the Office of Management and Budget, Reports Management Room 3208, New Executive Office Building, Washington, D. C. 20503.

Sincerely,

/s/SAVarga

Steven A. Varga, Chief
Operating Reactors Branch No. 1
Division of Licensing

Enclosure:
Request for Additional
Information

ORB#1:DL
CParrish
03/11/85

ORB#1:DL
DMcDonald/ts
03/06/85

BC-ORB#1:DL
SAVarga
03/11/85

8503260017 850311
PDR ADOCK 05000250
P PDR



1941

1942

1943

1944

1945

1946

1947

1948



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

March 11, 1985

Docket Nos. 50-250
and 50-251

Mr. J. W. Williams, Jr., Vice President
Nuclear Energy Department
Florida Power and Light Company
Post Office Box 14000
Juno Beach, Florida 33408

Dear Mr. Williams:

Reference: TAC Numbers 53726, 53727, 54036 and 54037


SUBJECT: REQUEST FOR ADDITIONAL INFORMATION FOLLOWING PRELIMINARY
STAFF REVIEW OF TURKEY POINT UNITS 3 AND 4 RESPONSES TO
- - - - -
GENERIC LETTER 83-28

The staff has completed a preliminary review to assess the completeness and adequacy of licensee responses to Generic Letter 83-28 Items 2.1, 2.2, 3.1.3, 3.2.3, 4.4 and 4.5. For the Turkey Point Plant, your responses were found to be incomplete for Items 2.2.2 and 4.5.3. Brief descriptions of the deficiencies are given as guidelines for corrective action in the enclosed request for additional information. Efforts by Owners Groups, INPO and NSSS Vendors have been or are being made to produce generic responses that may be useful in meeting the requirements of the above items. You may wish to contact your Owner's Group or INPO regarding the applicability of such generic responses to your plant.

In order to preserve our present review schedule, the staff needs to have the supplementary information within 60 days for Item 2.2.2, and within 90 days for Item 4.5.3. We request your cooperation in meeting this schedule.

This request for additional information was approved by the Office of Management and Budget under clearance number 3150-0011 which expires April 30, 1985. Comments on burden and duplication may be directed to the Office of Management and Budget, Reports Management Room 3208, New Executive Office Building, Washington, D. C. 20503.

Sincerely,


Steven A. Varga, Chief
Operating Reactors Branch No. 1
Division of Licensing

Enclosure:
Request for Additional
Information

J. W. Williams, Jr.
Florida Power and Light Company

Turkey Point Plants
Units 3 and 4

cc: Harold F. Reis, Esquire
Newman and Holtzinger, P.C.
1615 L Street, N.W.
Washington, DC 20036

Administrator
Department of Environmental
Regulation
Power Plant Siting Section
State of Florida
2600 Blair Stone Road
Tallahassee, Florida 32301

Mr. Jack Shreve
Office of the Public Counsel
Room 4, Holland Building
Tallahassee, Florida 32304

James P. O'Reilly
Regional Administrator, Region II
U.S Nuclear Regulatory Commission
Suite 2900
101 Marietta Street
Atlanta, GA 30303

Norman A. Coll, Esquire
Steel, Hector and Davis
4000 Southeast Financial
Center
Miami, Florida 33131-2398

Martin H. Hodder, Esquire
1131 N.E. 86th Street
Miami, Florida 33138

Mr. Ken N. Harris, Vice President
Turkey Point Nuclear Plant
Florida Power and Light Company
P.O. Box 029100
Miami, Florida 33102

Joette Lorion
7269 SW 54 Avenue
Miami, Florida 33143

Mr. M. R. Stierheim
County Manager of Metropolitan
Dade County
Miami, Florida 33130

Mr. Chris J. Baker, Plant Manager
Turkey Point Nuclear Plant
Florida Power and Light Company
P.O. Box 029100
Miami, Florida 33102


Resident Inspector
Turkey Point Nuclear Generating Station
U.S. Nuclear Regulatory Commission
Post Office Box 57-1185
Miami, Florida 33257-1185

Attorney General
Department of Legal Affairs
The Capitol
Tallahassee, Florida 32304

Regional Radiation Representative
EPA Region IV
345 Courtland Street, N.W.
Atlanta, GA 30308

Mr. Allan Schubert, Manager
Public Health Physicist
Department of Health and
Rehabilitative Services
1323 Winewood Blvd.
Tallahassee, Florida 32301

Intergovernmental Coordination
and Review
Office of Planning & Budget
Executive Office of the Governor
The Capitol Building
Tallahassee, Florida 32301



ENCLOSURE

Request for Additional Information
Turkey Point Plant Units 3 and 4

Item 2.2.2 - Incomplete

The licensee's response is based on the NUTAC report. The licensee needs to present his evaluation of the NUTAC program and describe how it will be implemented at Dresden 2,3. The staff found that the NUTAC program fails to address the concern about establishing and maintaining an interface between all safety-related equipment vendors and the utility. Accordingly, the licensee will need to supplement his response to address this concern. This additional information should describe how current procedures will be modified and new ones initiated to meet the elements of this concern.

Item 4.5.3 - Incomplete

The staff finds that modifications are not required to permit on-line testing of the backup scram valves. However, the staff concludes that testing of the backup scram valves (including initiating circuitry) at a refueling outage frequency, in lieu of on-line testing, is appropriate and should be included in the technical specification surveillance requirements. The licensee needs to address this conclusion.

Regarding the scram pilot valves (including all initiating circuitry), the licensee needs to provide the results of a review of existing or proposed intervals for on-line testing considering the concerns of sub-items 4.5.3.1 to 4.5.3.5 of the generic letter. The response shall show how these intervals result in high reactor trip system availability and present proposed technical specification changes for staff review.