## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8805090374 DOC.DATE: 88/04/28 NOTARIZED: NO DOCKET # FACIL:50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251 AUTH.NAME AUTHOR AFFILIATION CHRISTENSEN, H. Region 2, Ofc of the Director RECIP.NAME RECIPIENT AFFILIATION

DISTRIB	: PNO-II-88-029:on leakage. UTION CODE: IE34D Preliminary Notifi	COPIES	RECEI	ved:ltr O encl /	, SIZE:	. 1	R s Even
NOTES:					1		D
	RECIPIENT ID CODE/NAME	COPIES LTTR E		RECIPIENT ID CODE/NAME	COPI LTTR		S
INTERNAL:	AEOD/DSP/TPAB NRR/DOEA/EAB 11 NRR/DRIS/SIB 9A NUDOCS-ABSTRACT REG FILE 02	1 1 1 1	1 1 1 1	NRC OP CNTR NRR/DRIS/SGB 9A NRR/PMAS/ILRB12 OE LIEBERMAN,J RES BROOKS,B	1 1 1 1	1 1 1 1	A D
	RES-DEPY RES/DE RES/DRA RES/DRPS RGN2 FILE 01	1 1 1 1	1 1 1 1	RES FILE RES/DE/EIB RES/DRAA RES/PMPDAS	1 1 1	1 1 1	D S
EXTERNAL:	DOE BARBER EV34	1	1.	LPDR	1	1	

NSIC

R I

D

S

,

\_

D D

0

0

REQUIRED: LTTR 2/3 ENCL 23

TOTAL NUMBER OF COPIES REQUIRED: LTTR

NRC PDR

## PRELIMINARY NOTIFICATION OF EVENT OR UNUSUAL OCCURRENCE PNO-II-88-29

This preliminary notification constitutes EARLY notice of events of POSSIBLE safety or public interest significance. The information is as initially received without verification or evaluation, and is basically all that is known by the Region II staff on this

FACILITY:	Florida Power and Light Company	Licensee Emergency Classification:
×,	Turkey Point Unit 4	Notification of Unusual Event
	Docket No. 50-251	Alert
	Homestead, Florida	Site Area Emergency
	•	General Emergency
		X Not Applicable

SUBJECT: PLANT SHUTDOWN EXCEEDING 48 HOURS

On April 27, 1988, at 8:08 p.m. (EDT), the licensee commenced a shutdown of the unit due to increasing reactor coolant system (RCS) leakage. The leak rate increased to 3.1 gallons per minute (gpm) and was due to a leaking pressurizer spray valve. The Technical Specification limit for identified leakage is 10 gpm.

The licensee reports that the reactor was shutdown by 12:29 a.m. (EDT) on April 28 (today). The unit will be off-line for approximately ten (10) days.

The resident inspectors will conduct routine followup.

The State of Florida will be informed.

The NRC received initial notification of this event via telephone from the resident inspector to Region II at 8:00 a.m. (EDT) on April 28.

CONTACT: H. Christensen - 242-4197

## DISTRIBUTION

01

One White	M'land Nat'l	= μ	•
Flint North	<u>Bank Bldg</u>	Regions MAIL TO: Region I — \$55	DCS (Original IE 34)
Chairman Zech	ARM	Region I 8.58	DOT (Transportation Only)
Comm. Roberts		Region II.	. ,
Comm. Bernthal	AEOD	Region II. Region III-BFAX TO: Region IV-EST, Region V-ESC	INPO - PICT
Comm. Carr		Region IV - 55.1-10	NSAC
Comm. Rogers		Region V — とうど	RRI
SECY	Nicholson Lane		NRC OC
OGC	RES		LICENSEE (Reactor Licensee)
OCA			NRC HQ OPERATIONS CENTER
GPA/SLITP/PA	•		
EDO ·	H Stroot	$\sim$	•

(iconsec: - Gill **NRR** PDR NMSS

5520: 4/28/88 @ 4:00 TO REGIONS AND HQ

ACRS

8805090374 880428 PNO-II-88-029