

ACCELERATED DOCUMENT DISTRIBUTION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9306020246 DOC. DATE: 93/05/17 NOTARIZED: YES DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH. NAME AUTHOR AFFILIATION
 PLUNKETT, T.F. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Documents completion of Requested Action Items 1 & 2 of NRC
 Bulletin 90-001, Suppl 1, "Loss of Fill-Oil in Transmitters
 Mfg by Rosemount."

DISTRIBUTION CODE: IE39D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: NRC Bulletin 90-001, Loss of Fill Oil in Transmitters Mfg by Rosemount

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTR	ENCL		ID CODE/NAME		LTR	ENCL
	PD2-2 PD		1	1		RAGHAVAN, L		1	1
INTERNAL:	NRR LE, N		1	1		NRR/DORS/OGCB		1	1
	NRR/HFGB		1	1		NRR/OEAB		2	2
	<u>REG FILE</u> 02		1	1		RES/EMEB		1	1
	RGN2 FILE 01		1	1					
EXTERNAL:	NRC PDR		1	1		NSIC		1	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 12 ENCL 0

R
I
D
S
/
A
D
D
S
/
A
D
D
S



FPL

MAY 17 1993

L-93-138
10 CFR 50.54 (f)

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
NRC Bulletin 90-01, Supplement 1
Loss of Fill-Oil in Transmitters
Manufactured by Rosemount

NRC Bulletin 90-01, Supplement 1, "Loss of Fill-Oil in Transmitters Manufactured by Rosemount", issued December 22, 1992, requested that licensees take appropriate corrective actions for Rosemount transmitters which may be leaking fill-oil. NRC Bulletin 90-01, Supplement 1, includes all Model 1153 Series B, Model 1153 Series D, and Model 1154 transmitters manufactured by Rosemount before July 11, 1989.

By Florida Power and Light Company (FPL) letter L-93-41, dated March 3, 1993, FPL provided the response to NRC Bulletin 90-01, Supplement 1, for Turkey Point Nuclear. In accordance with FPL's response to Reporting Requirement 2.b of NRC Bulletin 90-01, Supplement 1, the enhanced surveillance program for Turkey Point Units 3 and 4 was implemented on April 6, 1993.

In accordance with Reporting Requirement 2.c of NRC Bulletin 90-01, Supplement 1, this letter documents Turkey Point Nuclear's completion of Requested Action Items 1 and 2 of the bulletin.

Should there be any questions, please contact us.

Very truly yours,

T. F. Plunkett
Vice President
Turkey Point Nuclear

TFP/OIH

cc: Stewart D. Ebnetter, Regional Administrator, Region II, USNRC
R. C. Butcher, Senior Resident Inspector, USNRC, Turkey Point Plant

020045

9306020246 930517
PDR ADOCK 05000250
Q PDR

Handwritten: DE39 1/0

STATE OF FLORIDA)
) ss.
COUNTY OF DADE)

T. F. Plunkett being first duly sworn, deposes and says:

That he is Vice President, Turkey Point Nuclear,
of Florida Power and Light Company, the Licensee herein;

That he has executed the foregoing document; that the statements
made in this document are true and correct to the best of his
knowledge, information and belief, and that he is authorized to
execute the document on behalf of said Licensee.

T. F. Plunkett

T. F. Plunkett

Subscribed and sworn to before me this

14 day of May, 1993.

Cheryl A. Kelly

Name of Notary Public (Type or Print)
NOTARY PUBLIC, in and for the County of
Dade, State of Florida



My Commission expires _____
Commission No. _____

T. F. Plunkett is personally known to me.