

PRIORITY 2

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)
(NUDOCS OFFSITE FACILITY)

ACCESSION NBR: 9411090018 DOC. DATE: 94/10/31 NOTARIZED: NO DOCKET #
ACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251

AUTH. NAME AUTHOR AFFILIATION
BOGER, B.A. Region 2 (Post 820201)
RECIP. NAME RECIPIENT AFFILIATION
GOLDBERG, J.H. Florida Power & Light Co.

SUBJECT: Discusses 941006 mgt meeting at plant site re NRC
presentation of SALP repts 50-250/94-99 & 50-251/94-99 at
facility during period of 930131-940923. List of attendees
& handout encl.

DISTRIBUTION CODE: IE40D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 15
TITLE: Systematic Assessment of Licensee Performance (SALP) Report

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTR	ENCL		ID CODE/NAME		LTR	ENCL
	PD2-2 LA		1	1		PD2-2 PD		1	1
	CROTEAU, R		1	1					
INTERNAL:	COMMISSION		5	5		DEDRO		1	1
	FILE CENTER-02		1	1		NRR/DORS/OEAB		1	1
	NRR/DRCH/HHFBPT		1	1		NRR/DRCH/HOLB		1	1
	NRR/DRIL/RSIB		1	1		NRR/DRSS/PEPB		1	1
	NRR/DRSS/PRPB		1	1		NRR/DRSS/RSGB		1	1
	NRR/PMAS/IRCB-E		1	1		NUDOCS-ABSTRACT		1	1
	OE DIR		1	1		OGC/HDS3		1	1
	RES/HFB		1	1		RGN2 FILE 01		1	1
EXTERNAL:	L ST LOBBY WARD		1	1		LITCO BRYCE, J H		1	1
	NOAC		1	1		NRC PDR		1	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL
DESK, ROOM P1-37 (EXT. 504-2083) TO ELIMINATE YOUR NAME FROM
DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 27 ENCL 27

P
R
I
O
R
I
T
Y

2

D
O
C
U
M
E
N
T



October 31, 1994

Florida Power and Light Company
ATTN: Mr. J. H. Goldberg
President - Nuclear Division
P. O. Box 14000
Juno Beach, FL 33408-0420

SUBJECT: MEETING SUMMARY - TURKEY POINT
SYSTEMATIC ASSESSMENT OF LICENSE PERFORMANCE (INSPECTION
REPORT NO 50-250/94-99 AND 50-251/94-99)

Gentlemen:

This refers to the management meeting conducted at the Turkey Point site on October 6, 1994. The purpose of the meeting was for the Nuclear Regulatory Commission to present the Systematic Assessment of Licensee Performance (SALP) of the Turkey Point facility during the period of January 31, 1993, through August 27, 1994. The SALP Report was issued on September 23, 1994, and covered the performance of Plant Operations, Maintenance, Engineering and Plant Support activities at your Turkey Point facility. A list of attendees and a copy of your handout are enclosed.

Thank you for your response of October 10, 1994, to our SALP Report. We appreciate your response and attention to the assessment results.

In accordance with Section 2.790 of NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosures will be placed in the NRC Public Document Room.

Should you have any questions concerning this matter, please contact us.

Sincerely,

Orig signed by Bruce A. Boger

Bruce A. Boger, Acting Director
Division of Reactor Projects

Docket Nos. 50-250, 50-251
License Nos. DPR-31, DPR-41

Enclosures: 1. List of Attendees
2. SALP Handout
3. Response to SALP

cc w/encls: See page 2

OFFICIAL COPY

680036
9411090018 941031
PDR ADCK 05000250
PDR

IE40



cc w/encls:
H. N. Paduano, Manager
Licensing & Special Programs
Florida Power and Light Company
P. O. Box 14000
Juno Beach, FL 33408-0420

L. W. Pearce
Plant General Manager
Turkey Point Nuclear Plant
P. O. Box 029100
Miami, FL 33102

T. F. Plunkett
Site Vice President
Turkey Point Nuclear Plant
P. O. Box 029100
Miami, FL 33102

T. V. Abbatiello
Site Quality Manager
Turkey Point Nuclear Plant
P. O. Box 029100
Miami, FL 33102

E. J. Weinkam
Licensing Manager
Turkey Point Nuclear Plant
P. O. Box 4332
Miami, FL 33032-4332

Harold F. Reis, Esq.
Newman and Holtzinger, P.C.
1615 L Street, NW
Washington, D. C. 20036

John T. Butler, Esq.
Steel, Hector and Davis
4000 Southeast Financial Center
Miami, FL 33131-2398

Attorney General
Department of Legal Affairs
The Capitol
Tallahassee, FL 32304
cc w/encls: Continued see page 3



cc w/encls: Continued
 Bill Passetti
 Office of Radiation Control
 Department of Health and
 Rehabilitative Services
 1317 Winewood Boulevard
 Tallahassee, FL 32399-0700

Jack Shreve
 Public Counsel
 Office of the Public Counsel
 c/o The Florida Legislature
 111 West Madison Avenue, Room 812
 Tallahassee, FL 32399-1400

Joaquin Avino
 County Manager of Metropolitan
 Dade County
 111 NW 1st Street, 29th Floor
 Miami, FL 33128

Joe Myers, Director
 Division of Emergency Preparedness
 Department of Community Affairs
 2740 Centerview Drive
 Tallahassee, FL 32399-2100

Distribution w/encls:
 R. Croteau, NRR
 G. Hallstrom, RII
 PUBLIC

Thomas P. Johnson
 Senior Resident Inspector
 U.S. Nuclear Regulatory Commission
 P. O. Box 1448
 Homestead, FL 33090

*FOR PREVIOUS CONCURRENCE 'SEE ATTACHED

SEND	OFC	RII	RII	RII <i>MB</i>		
TO	NAME	RSchin *	KLandis *	DVerrelli		
PDR?	DATE	10/ /94	10/ /94	10/31 /94	/ /94	/ /94
Yes	No	COPY?	Yes	No	Yes	No
			Yes	No	Yes	No

OFFICIAL RECORD COPY

DOCUMENT NAME: G:\TPMTGSUM

cc w/encls: Continued
 Jack Shreve
 Public Counsel
 Office of the Public Counsel
 c/o The Florida Legislature
 111 West Madison Avenue, Room 812
 Tallahassee, FL 32399-1400

Joaquin Avino
 County Manager of Metropolitan
 Dade County
 111 NW 1st Street, 29th Floor
 Miami, FL 33128

Joe Myers, Director
 Division of Emergency Preparedness
 Department of Community Affairs
 2740 Centerview Drive
 Tallahassee, FL 32399-2100

Distribution w/encls:

R. Croteau, NRR
 G. Hallstrom, RII
 PUBLIC

Thomas P. Johnson
 Senior Resident Inspector
 U.S. Nuclear Regulatory Commission
 P. O. Box 1448
 Homestead, FL 33090

SEND	OFC	RII	RII	RII			
TO	NAME	RSchin <i>KOP</i>	KLandis <i>KOP</i>	OVerrelli			
PDR?	DATE	10/27/94	10/27/94	10/ /94	/ /94	/ /94	
Yes	No	COPY? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Yes	No	Yes	No

OFFICIAL RECORD COPY

DOCUMENT NAME: G:\TPMTGSUM

List of Attendees

Florida Power and Light Company

J. H. Goldberg, President
T. F. Plunkett, Site Vice President
W. H. Bohlke, Vice President, Engineering and Licensing
L. W. Pearce, Plant General Manager

Nuclear Regulatory Commission

S. D. Ebnetter, Regional Administrator, Region II (RII)
B. A. Boger, Acting Director, Division of Reactor Projects (DRP), RII
D. M. Verrelli, Chief, DRP Branch 2, RII
T. P. Johnson, Senior Resident Inspector, DRP, RII
H. N. Berkow, Director, Project Directorate II-3, Office of Nuclear Reactor
Regulation (NRR)
R. P. Croteau, Project Manager, NRR

Enclosure 1

**UNITED STATES
NUCLEAR REGULATORY
COMMISSION**



TURKEY POINT NUCLEAR PLANT


January 31, 1993 - August 27, 1994

**SYSTEMATIC ASSESSMENT OF
LICENSEE PERFORMANCE
(SALP)**

MEETING

October 6, 1994

NEW SALP PROCESS



FUNCTIONAL AREAS FOR **OPERATING REACTORS**

- 1. PLANT OPERATIONS**
- 2. MAINTENANCE**
- 3. ENGINEERING**
- 4. PLANT SUPPORT**
 - Radiological Controls**
 - Emergency Preparedness**
 - Security**

TURKEY POINT NUCLEAR PLANT

SALP BOARD MEMBERS

Bruce A. Boger	Acting Director (Chairperson) Division of Reactor Projects Region II
Albert F. Gibson	Director Division of Reactor Safety Region II
J. Philip Stohr	Director Division of Radiation Safety and Safeguards Region II
Herbert N. Berkow	Director Project Directorate II-3 Office of Nuclear Reactor Regulation

PERFORMANCE CATEGORY RATINGS

Category 1.

Licensee attention and involvement have been properly focused on safety and resulted in a superior level of performance. Licensee programs and procedures have provided effective controls. The licensee's self-assessment efforts have been effective in the identification of emergent issues. Corrective actions are technically sound, comprehensive, and thorough. Recurring problems are eliminated, and resolution of issues is timely. Root cause analyses are thorough.

Category 2.

Licensee attention and involvement are normally well focused and resulted in a good level of safety performance. Licensee programs and procedures normally provide the necessary control of activities, but deficiencies may exist. The licensee's self-assessments are normally good, although issues may escape identification. Corrective actions are usually effective, although some may not be complete. Root cause analyses are normally thorough.

Category 3.

Licensee attention and involvement have resulted in an acceptable level of safety performance. However, licensee performance may exhibit one or more of the following characteristics. Licensee programs and procedures have not provided sufficient control of activities in important areas. The licensee's self-assessment efforts may not occur until after a potential problem becomes apparent. A clear understanding of the safety implications of significant issues may not have been demonstrated. Numerous minor issues combine to indicate that the licensee's corrective action is not thorough. Root cause analyses do not probe deep enough, resulting in the incomplete resolution of issues. Because the margin to unacceptable performance in important aspects is small, increased NRC and licensee attention is required.

TURKEY POINT NUCLEAR PLANT

SALP RATING SUMMARY

FUNCTIONAL AREA	RATING LAST PERIOD	RATING THIS PERIOD
PLANT OPERATIONS	1	1
MAINTENANCE	2 (I)	1
ENGINEERING	2 (I)	1
PLANT SUPPORT	N/A	1
EMERGENCY PREPAREDNESS	1	
RADIOLOGICAL CONTROLS	1	
SECURITY	1	
SAFETY ASSESSMENT/ QUALITY VERIFICATION	1	

TURKEY POINT SALP MEETING

PLANT OPERATIONS

STRENGTHS:

- **OPERATOR PERFORMANCE**
- **MANAGEMENT AND QUALITY ASSURANCE
OVERSIGHT AND CONSERVATISM**
- **MANAGEMENT OF HIGH RISK ACTIVITIES**
- **TEAMWORK WITH OTHER ORGANIZATIONS**
- **ROOT CAUSE AND CORRECTIVE ACTION
PROGRAMS**

CHALLENGES:

- **CONTROL ROOM OVERSIGHT OF FIELD
ACTIVITIES**

TURKEY POINT SALP MEETING

MAINTENANCE

STRENGTHS:

- **OVERALL MAINTENANCE PROGRAM MANAGEMENT**
- **BACKLOG MANAGEMENT**
- **INTRA- AND INTER- ORGANIZATION COORDINATION**
- **MAINTENANCE CONTRIBUTION TO EQUIPMENT RELIABILITY AND PLANT AVAILABILITY**

CHALLENGES:

- **INCREASE EMPHASIS ON MAINTAINING BALANCE OF PLANT EQUIPMENT**

TURKEY POINT SALP MEETING

ENGINEERING

STRENGTHS:

- **TEAMWORK**
- **BACKLOG MANAGEMENT**
- **DRAWINGS**
- **OPERATIONS SUPPORT.**
- **MAINTENANCE SUPPORT**
- **CONTRACTOR OVERSIGHT**
- **PLANNING AND PRIORITIZATION**
- **SELF-ASSESSMENT**

CHALLENGES:

- **CONTINUED FOCUS ON OPERATIONS SUPPORT**

TURKEY POINT SALP MEETING

PLANT SUPPORT

STRENGTHS:

- **ALARA PROGRAM AND EXPOSURE CONTROL**
- **EMERGENCY PREPAREDNESS**
 - **TRAINING**
 - **FACILITIES AND EQUIPMENT**
 - **INTERACTION WITH OFFSITE AGENCIES**
- **SECURITY AND FITNESS FOR DUTY PROGRAMS**
- **AUDITS**
 - **PHYSICAL SECURITY**
 - **RADIOLOGICAL CONTROLS**

CHALLENGES:

- **CONTINUED ATTENTION TO DETAIL**
 - **RADIOLOGICAL CONTROLS**