

# CATEGORY 1

200 COPY

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9702030201 DOC. DATE: 97/01/29 NOTARIZED: NO DOCKET #  
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250  
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251  
 AUTH. NAME: HOVEY, R.J. AUTHOR AFFILIATION: Florida Power & Light Co.  
 RECIP. NAME: RECIPIENT AFFILIATION: Document Control Branch (Document Control Desk)

SUBJECT: Forwards rev 32 to "Radiological Emergency Plan."

DISTRIBUTION CODE: A045D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2 + 144  
 TITLE: OR Submittal: Emergency Preparedness Plans, Implement'g Procedures, C

### NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
	PD2-3 PD	1 1	CROTEAU, R	1 1
INTERNAL:	FILE CENTER 01	2 2	NRR/DRPM/PERB	1 1
	NUDOCS-ABSTRACT	1 1		
EXTERNAL:	NOAC	1 1	NRC PDR	1 1

REPLACED BY NEW  
 REV 32 dtd 2/11/97

NOTE TO ALL "RIDS" RECIPIENTS:  
 PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM OWFN 5D-5 (EXT. 415-2083) TO ELIMINATE YOUR NAME FROM  
 DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 8 ENCL 8

C  
A  
T  
E  
G  
O  
R  
Y  
  
1  
  
D  
O  
C  
U  
M  
E  
N  
T



L-97-023  
10 CFR 50.54(q)  
10 CFR 50, Appendix E

U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D. C. 20555

Re: Turkey Point Units 3 and 4  
Docket Nos. 50-250 and 50-251  
Radiological Emergency Plan - Revision 32

Florida Power and Light Company (FPL) has issued Revision 32 to the Turkey Point Radiological Emergency Plan, and has determined that the revision does not decrease the effectiveness of the plan. The changes are based on (1) achieving better consistency between the Turkey Point and St. Lucie Emergency Plans, (2) reflecting recent changes at Turkey Point and in the state and county organizations, (3) correcting an omission to the Emergency Classification table, and (4) satisfying the commitment made by FPL in our letter L-96-309, to better describe the role of drills and exercises in Emergency Response training.

Attached is a description of the changes to the Turkey Point Radiological Emergency Plan. Pursuant to 10 CFR 50.54 (q), enclosed is one copy of the plan.

Should there be any questions, please contact us.

Very truly yours,

R. J. Hovey  
Vice President  
Turkey Point Plant

CLM

attachment  
enclosures

030040

cc: Luis A. Reyes, Regional Administrator, Region II, USNRC (2 copies)  
T. P. Johnson, Senior Resident Inspector, USNRC, Turkey Point Plant (no enclosure)

9702030201 970129  
PDR ADOCK 05000250  
F PDR

**TURKEY POINT RADIOLOGICAL EMERGENCY PLAN  
SUMMARY OF CHANGES IN REVISION 32**

The changes for revision 32 of the Turkey Point Radiological Emergency Plan are summarized as follows:

Step 7.2.2 has been clarified to better describe the role of drills and exercises in Emergency Response training.

Section 7.3 has been revised to ensure the intent of previous Technical Specification requirements for the Emergency Plan Implementing procedures has been clearly transferred to the Turkey Point Radiological Emergency Plan.

The organization change combining supervisory duties of Health Physics and Chemistry Departments has been reflected in the document.

"Chemistry Representative" and "other trained ERO personnel on-shift" have been added to sections describing the On-shift Response Organization.

Relocation of the Monroe County Emergency Operations Center, from Plantation Key to Key Largo, has been reflected in the document.

Department of Health and Rehabilitative Services - Office of Radiation Control is now Department of Health - Bureau of Radiation Control. This has been changed, as appropriate, throughout the document.

Correction to Table 3-1, Emergency Classification Table, Item 13: under Unusual Event, Paragraph E was erroneously omitted in a previous revision. The implementing procedure (O-EPIP-20101) was and remains correct.

Various other minor editorial changes have been made, primarily to fix titles and typographical errors.